

Summerside

WATER SYSTEM REPORT

2019

Prepared By

Municipal Services - City of Summerside

Contents

Introduction	3
Summary	3
Bacteria Testing Results	5
Chemistry Analysis	5
Chlorination of Water System.....	5
Statistic Summary	6
Conclusion.....	6
Suggested Reading Material	7

Water System Report
January 1 – December 31, 2019
City of Summerside, Prince Edward Island
Department of Municipal Services

Introduction

The City of Summerside began sampling and testing drinking water on a bi-weekly basis in the 1960's. In 2001 Summerside established the present policy for water sampling. This policy ensures that the drinking water quality in Summerside is maintained according to the standards set out in the Guidelines for Canadian Drinking Water Quality. In unique situations which are not addressed by these Guidelines, the City is committed to follow the guidance of the PEI Chief Health Officer. This report fulfills the City's regulated requirement for summarizing system water quality on an annual basis and is intended to be public information.

Summary

City officials have divided the water distribution system into 8 representative areas. Water samples (one from each area as well as one from each active well) are collected and analyzed for bacteria every two weeks. The number of sample locations and frequency of sampling was determined in accordance with the Guidelines for Canadian Drinking Water Quality. **Table 1** lists below the most commonly used sample locations for 2019.

Sample Location	Civic Address (Summerside, P.E.I.)	City Sampling Zone
St. Eleanor's Community Center	1 West Drive	1
Bernard's Quick Mart	126 Bayview Drive	1
Waste Water Treatment Plant	15 Seaweed Road	2
Illsley's Feed Store	61 Mill Crescent	2
Summerset Manor (Utility Room)	15 Frank Mellish Street	3
Lions Club Senior's Residence	326 Brophy Avenue	4
Summerside Fire Hall Station #1	251 Foundry Street	5
ADL	79 Water Street	6
Ben's Bakery Outlet Store	686 Water Street East	7
Read's Corner Tim Horton's	820 Water Street East	8
City Water Source Location		
S1 Well	411 Northmarket Street	6
S7 Well	123 Walker Avenue	3
S8 Well (Not active in 2019)	507 MacEwen Road	3
S10 Well	277 Greenwood Drive	2
SE4 Well	26 Briggs Street	1
Wilmot Well Field (2 active wells)	855 Read Drive	8

SE # 1	156 South Drive	1
St Eleanor's Wellfield (3 Wells)	80 Bayview Drive	2

Table 1: Water Sample Locations

The sampling zones listed in Table 1 are shown below in **Figure 1: Summerside Water Sample Areas**. These 8 sampling zones were selected according to the EPA Drinking Water and Wastewater Facility Operating Regulations. If any of the regular sampling locations are inaccessible to City staff on a scheduled sampling day, an alternate location from the same zone is sampled as a substitute.



Figure 1: Summerside Water Sample Areas

Following collection, all water samples are sent to the Provincial Department of Environment Analytical Laboratory in Charlottetown. Each sample is tested for Total Coliforms DC and Escherichia Coli DC (E. Coli). In addition to the bacteria tests which are performed at the Provincial lab, the Free Chlorine Residual is analyzed and recorded by City Staff at the time of sample collection, as required by section 11(1)(e) of the Drinking Water and Wastewater Facility Operating Regulations.

Bacteria Testing Results

During the 2019 year 503 water samples from the City of Summerside water distribution system and wells were tested for Bacteria at the P.E.I. Analytical Laboratory. Of these 503 samples, 487 were taken from the public drinking water system as regular testing. The remaining 16 samples were taken because of requests from customers for testing services. 100% of samples taken for customer requests passed the requirements for the Guidelines for Canadian Drinking Water. There were also 34 samples which showed non-zero bacteria counts in 2019. No water was declared unfit to drink.

Chemistry Analysis

The EPA Drinking Water and Wastewater Facility Operating Regulations require all active wells to be subject to chemical analysis. A general chemical analysis of each well must be performed semi-annually and a detailed analysis every three years. All water chemistry analysis for Summerside is performed at the Provincial Analytical Laboratory. The Guidelines for Canadian Drinking Water Quality set a Maximum Allowable Concentration (MAC) for various chemical contents of drinking water.

General chemistry analysis on water from all of Summerside's active wells was performed on April 9 and November 19, 2019 and included in this report. As shown in the general chemistry spreadsheet, all wells contained water which falls within the Health Canada Guidelines for drinking water – that is to say that no water sample collected exceeded the Maximum Allowable Concentration (MAC) for any chemical component.

Summerside performs detailed chemical analysis on wells on a 3 year rotation as required by the province. These tests were performed in 2017 and will be performed again in 2020. Testing in 2019 showed that all water samples from all Summerside wells are compliant with Health Canada Guidelines for healthy drinking water.

During 2019 City of Summerside staff collected 98 samples for nitrate analysis. The Guidelines for Canadian Drinking Water Quality set 10 mg/L as the Maximum Allowable Concentration for Nitrates. All samples taken during 2019 from the Summerside system were within the allowable limits. The lowest Nitrate value measured for 2019 was 2.5 parts per million (ppm) and the highest value measured was 8.7 ppm.

Chlorination of Water System

Drinking water in the Summerside system is subject to only 1 type of treatment. Chlorine (as sodium hypochlorite liquid) is applied at each well. The goal of chlorination is to maintain a

Free Chlorine Residual of at least 0.1 mg/L or higher at all points in the system at all times. This level of chlorination is the industry minimum standard for drinking water disinfection and is recommended by the Guidelines for Canadian Drinking Water Quality.

City Staff evaluate the free chlorine residual of each water sample used for bacteria testing. This means that on average 20 free chlorine residual tests are performed at the same locations as bacteria tests on a biweekly basis. Chlorine Residuals are also tested at each well 3 or 4 times per week. During 2019 the lowest chlorine level measured was 0.12 mg/L and the highest was 1.06 mg/L. Chlorine readings are shown in the Microchemistry spreadsheet and although these two values represent the highest and lowest measurements for the year they are by no means the typical measurements and the spreadsheet should be consulted for more information. Therefore, all chlorine residuals were within acceptable levels.

Statistic Summary

Statistic	Value for 2019
Samples Tested for Bacteria	503
Bacteria Tests done at Customer Request	16 (100% pass rate)
Bacteria Tests with non-zero results	34
Nitrate Samples Tested	98 (100% pass rate)
General Chemistry Tests	54– 100% pass rate
Highest Nitrate Concentration	8.7 ppm (10ppm allowable maximum)
Lowest Nitrate Concentration	2.5 ppm
Sampling Areas	8
Number of Active Wells in System (During the 2019 reporting year)	10
Highest Chlorine Residual Measured	1.06mg/L
Lowest Chlorine Residual Measured	0.12mg/L (0.1 minimum recommended)

Table 2: Statistic Summary for Summerside 2019

Table 2 Summarizes statistics for the Summerside water system for 2019. Please note that 3 spreadsheets of test results (Bacteria testing, Nitrate monitoring, and General Well Chemistry) are available on the City website. For help understanding results please feel free to contact the City.

Conclusion

The City of Summerside Municipal Works department continues to operate and maintain a safe water utility, delivering water which meets the Canadian Drinking Water Guidelines as set out

by Health Canada. The public are welcome to contact the Municipal Services Director at 902-432-1272 with any questions.

Suggested Reading Material

1. **Bacterial Drinking Water Analysis**

This brochure was prepared by the PEI Department of Environment and explains how water samples are tested for bacteria on PEI. The handout also explains what types of bacteria are tested for and what the test results mean. <http://www.gov.pe.ca/photos/original/watertest.pdf>

2. **Guidelines for Canadian Drinking Water Quality (Health Canada)**

This detailed document lists the Maximum Allowable Concentration of numerous components which we test our water for.

<http://www.hc-sc.gc.ca/ewh-semt/water-eau/drink-potab/guide/index-eng.php>

Summerside

Guideline to Nitrate Analysis:

Units for Nitrate are mg/L

Nitrate Maximum Allowable Concentration is 10.0 ppm.

	Sample ID	Location	Date
NO.	1.0	P190108036 Summerside Firehall (Station #1)	08-Jan-19
NO.	2.0	P190108037 ADL	08-Jan-19
NO.	3.0	P190108042 Wilmot Wellfield Pipe Gallery	08-Jan-19
NO.	4.0	P190122044 Summerside Firehall (Station #1)	22-Jan-19
NO.	5.0	P190122045 ADL	22-Jan-19
NO.	6.0	P190122050 Wilmot Wellfield Pipe Gallery	22-Jan-19
NO.	7.0	P190205062 Summerside Firehall (Station #1)	05-Feb-19
NO.	8.0	P190205063 ADL	05-Feb-19
NO.	9.0	P190205068 Wilmot Wellfield Pipe Gallery	05-Feb-19
NO.	10.0	P190219019 Summerside Firehall (Station #1)	19-Feb-19
NO.	11.0	P190219020 ADL	19-Feb-19
NO.	12.0	P190219025 Wilmot Wellfield Pipe Gallery	19-Feb-19
NO.	13.0	P190307051 Summerside Firehall (Station #1)	07-Mar-19
NO.	14.0	P190307052 ADL	07-Mar-19
NO.	15.0	P190307057 Wilmot Wellfield Pipe Gallery	07-Mar-19
NO.	16.0	P190319055 Summerside Firehall (Station #1)	19-Mar-19
NO.	17.0	P190319056 ADL	19-Mar-19
NO.	18.0	P190319061 Wilmot Wellfield Pipe Gallery	19-Mar-19
NO.	19.0	P190403059 Summerside Firehall (Station #1)	03-Apr-19
NO.	20.0	P190403060 ADL	03-Apr-19
NO.	21.0	P190403065 Wilmot Wellfield Pipe Gallery	03-Apr-19
NO.	22.0	P190409055 S7 Well	09-Apr-19
NO.	23.0	P190409056 S1 Well	09-Apr-19

NO.	24.0	P190409057	Wilmot Well Field Pipe Gallery	09-Apr-19
NO.	25.0	P190409058	S10	09-Apr-19
NO.	26.0	P190409059	SE4	09-Apr-19
NO.	27.0	P190409060	SE1	09-Apr-19
NO.	28.0	P190409061	St Eleanor's Wellfield #2	09-Apr-19
NO.	29.0	P190409062	St Eleanor's Wellfield #3	09-Apr-19
NO.	30.0	P190409063	Wilmot Well #2	09-Apr-19
NO.	31.0	P190409064	Wilmot Well #3	09-Apr-19
NO.	32.0	P190409065	Wilmot Well#4	09-Apr-19

NO.	33.0	P190418041	Summerside Firehall (Station #1)	18-Apr-19
NO.	34.0	P190418042	ADL	18-Apr-19
NO.	35.0	P190418047	Wilmot Wellfield Pipe Gallery (Well #3)	18-Apr-19

NO.	36.0	P190430055	Summerside Firehall (Station #1)	30-Apr-19
NO.	37.0	P190430056	ADL	30-Apr-19
NO.	38.0	P190430061	Wilmot Wellfield Pipe Gallery (Well #4)	30-Apr-19

NO.	39.0	P190514096	Summerside Firehall (Station #1)	14-May-19
NO.	40.0	P190514097	ADL	14-May-19
NO.	41.0	P190514102	Wilmot Wellfield Pipe Gallery (Well #4)	14-May-19

NO.	42.0	P190528087	Summerside Firehall (Station #1)	28-May-19
NO.	43.0	P190528088	ADL	28-May-19
NO.	44.0	P190528093	Wilmot Wellfield Pipe Gallery	28-May-19

NO.	45.0	P190611118	Summerside Firehall (Station #1)	11-Jun-19
NO.	46.0	P190611119	ADL	11-Jun-19
NO.	47.0	P190611124	Wilmot Wellfield Pipe Gallery	11-Jun-19

NO.	48.0	P190626116	Summerside Firehall (Station #1)	26-Jun-19
NO.	49.0	P190626117	ADL	26-Jun-19
NO.	50.0	P190626122	Wilmot Wellfield Pipe Gallery	26-Jun-19

NO.	51.0	P190710123	Summerside Firehall (Station #1)	10-Jul-19
NO.	52.0	P190710122	ADL	10-Jul-19
NO.	53.0	P190710117	Wilmot Wellfield Pipe Gallery	10-Jul-19

NO.	54.0	P190723084	Summerside Firehall (Station #1)	23-Jul-19
NO.	55.0	P190723085	ADL	23-Jul-19
NO.	56.0	P190723090	Wilmot Wellfield Pipe Gallery	23-Jul-19

NO.	55.0	P190806056	Summerside Firehall (Station #1)	06-Aug-19
NO.	56.0	P190806057	ADL	06-Aug-19
NO.	57.0	P190806062	Wilmot Wellfield Pipe Gallery	06-Aug-19

NO.	58.0	P19082095	Summerside Firehall (Station #1)	06-Aug-19
NO.	59.0	P19082096	ADL	06-Aug-19
NO.	60.0	P190820101	Wilmot Wellfield Pipe Gallery	06-Aug-19
NO.	61.0	P190903042	Summerside Firehall (Station #1)	03-Sep-19
NO.	62.0	P190903041	ADL	03-Sep-19
NO.	63.0	P190903036	Wilmot Wellfield Pipe Gallery	03-Sep-19
NO.	64.0	P190919093	Summerside Firehall (Station #1)	19-Sep-19
NO.	65.0	P190919094	ADL	19-Sep-19
NO.	66.0	P190919099	Wilmot Wellfield Pipe Gallery	19-Sep-19
NO.	67.0	P191001092	Summerside Firehall (Station #1)	01-Oct-19
NO.	68.0	P191001093	ADL	01-Oct-19
NO.	69.0	P191001098	Wilmot Wellfield Pipe Gallery	01-Oct-19
NO.	70.0	P191015044	Summerside Firehall (Station #1)	15-Oct-19
NO.	71.0	P191015045	ADL	15-Oct-19
NO.	72.0	P191015050	Wilmot Wellfield Pipe Gallery	15-Oct-19
NO.	73.0	P191029050	Summerside Firehall (Station #1)	29-Oct-19
NO.	74.0	P191029051	ADL	29-Oct-19
NO.	75.0	P191029056	Wilmot Wellfield Pipe Gallery	29-Oct-19
NO.	76.0	P191113100	Summerside Firehall (Station #1)	13-Nov-19
NO.	77.0	P191113094	Wilmot Wellfield Pipe Gallery	13-Nov-19
No.	78.0	P191119027	S1 Well	19-Nov-19
No.	79.0	P191119028	St Eleanor's Wellfield Well #1	19-Nov-19
No.	80.0	P191119029	St Eleanor's Wellfield Well #2	19-Nov-19
No.	81.0	P191119030	St Eleanor's Wellfield Well #3	19-Nov-19
No.	82.0	P191119031	SE4 Well	19-Nov-19
No.	83.0	P191119032	SE1 Well	19-Nov-19
No.	84.0	P191119033	S10 Well	19-Nov-19
No.	85.0	P191119034	S7 Well	19-Nov-19
No.	86.0	P191119035	Wilmot Wellfield Well #1	19-Nov-19
No.	87.0	P191119036	Wilmot Wellfield Well #2	19-Nov-19
No.	88.0	P191119037	Wilmot Wellfield Well #3	19-Nov-19
No.	89.0	P191119038	Wilmot Wellfield Well #4	19-Nov-19
NO.	90.0	P191126044	Summerside Firehall (Station #1)	26-Nov-19
NO.	91.0	P191126045	ADL	26-Nov-19
NO.	92.0	P191126050	Wilmot Wellfield Pipe Gallery (Well #3)	26-Nov-19
NO.	93.0	P191210075	Summerside Firehall (Station #1)	10-Dec-19
NO.	94.0	P191210076	ADL	10-Dec-19

NO.	95.0	P191210081	Wilmot Wellfield Pipe Gallery (Well #3)	10-Dec-19
NO.	96.0	P191227030	Summerside Firehall (Station #1)	27-Dec-19
NO.	97.0	P191227029	ADL	27-Dec-19
NO.	98.0	P191227024	Wilmot Wellfield Pipe Gallery (Well #3)	27-Dec-19



Address	City Sample Zone	Nitrate
---------	------------------	---------

251 Foundry Street	6	5.4
79 Water Street	7	5.9
855 Read Drive	8	4.2

251 Foundry Street	6	5.6
79 Water Street	7	6.2
855 Read Drive	8	4.2

251 Foundry Street	6	5.1
79 Water Street	7	5.1
855 Read Drive	8	7.6

251 Foundry Street	6	5.6
79 Water Street	7	5.9
855 Read Drive	8	7.5

251 Foundry Street	6	5.9
79 Water Street	7	6.1
855 Read Drive	8	7.7

251 Foundry Street	6	4.1
79 Water Street	7	5.4
855 Read Drive	8	3.9

251 Foundry Street	6	4.8
79 Water Street	7	6.2
411 Northmarket St	6	8.1

123 Walker Ave	3	3.6
411 Northmarket St	6	3.3

855 Read Dr	8	7.6
277 Greenwood Dr	2	2.6
26 Briggs St	1	5.2
152 South Dr	2	3.0
80 Bayview Dr	2	5.8
80 Bayview Dr	2	7.3
855 Read Dr	8	7.5
855 Read Dr	8	7.6
855 Read Dr	8	7.3

251 Foundry Street	6	4.7
79 Water Street	7	6.1
855 Read Drive	8	7.5

251 Foundry Street	6	3.3
79 Water Street	7	7.2
855 Read Drive	8	6.3

251 Foundry Street	6	5.1
79 Water Street	7	5.4
855 Read Drive	8	6.3

251 Foundry Street	6	3.8
79 Water Street	7	6.2
855 Read Drive	8	6.2

251 Foundry Street	6	5.3
79 Water Street	7	4.5
855 Read Drive	8	4.1

251 Foundry Street	6	5.6
79 Water Street	7	5.2
855 Read Drive	8	7.1

251 Foundry Street	6	3.3
79 Water Street	7	4.8
855 Read Drive	8	3.7

251 Foundry Street	6	5.3
79 Water Street	7	5.2
855 Read Drive	8	7.9

251 Foundry Street	6	3.6
79 Water Street	7	4.6
855 Read Drive	8	6.4

251 Foundry Street	6	5.4
79 Water Street	7	6.5
855 Read Drive	8	6.6

251 Foundry Street	6	3.5
79 Water Street	7	5.3
855 Read Drive	8	3.6

251 Foundry Street	6	5.5
79 Water Street	7	5.0
855 Read Drive	8	7.7

251 Foundry Street	6	5.4
79 Water Street	7	4.7
855 Read Drive	8	7.7

251 Foundry Street	6	5.5
79 Water Street	7	4.9
855 Read Drive	8	8.3

251 Foundry Street	6	5.8
79 Water Street	7	5.6
855 Read Drive	8	8.4

251 Foundry Street	6	4.7
855 Read Drive	8	7.8

411 North Market St	6	3.0
80 Bayview Dr	2	3.1
80 Bayview Dr	2	4.9
80 Bayview Dr	2	6.2
26 Briggs St	1	5.4
152 South Dr	2	2.7
277 Greenwood Dr	2	2.5
123 Walker Ave	3	3.3
855 Read Dr	8	8.0
855 Read Dr	8	4.6
855 Read Dr	8	8.6
855 Read Dr	8	7.1

251 Foundry Street	6	4.8
79 Water Street	7	5.5
855 Read Drive	8	8.7

251 Foundry Street	6	5.4
79 Water Street	7	5.6

855 Read Drive	8	8.6
----------------	---	-----

251 Foundry Street	6	5.3
79 Water Street	7	6.0
855 Read Drive	8	8.6

Summerside

	Health Canada MAC	Health Canda AO	
Sample ID			
Location			
Date			
Address			
City Sample Zone			
pH for Water	NA	7 to 10.5	Units pH
Alkalinity (ppm of CaCO ₃)	NA	NA	mg/L
Chloride	NA	250.0	mg/L
Barium dis	1	0	mg/L
Calcium dis	NA	NA	mg/L
Potassium dis	NA	NA	mg/L
Copper dis	NA	1	mg/L
Iron dis	NA	0.3	mg/L
Magnesium dis	NA	NA	mg/L
Manganese dis	NA	0.05	mg/L
Phosphorus dis	NA	NA	mg/L
Sodium dis	NA	200.0	mg/L
Sulfate calc from S dis	NA	500	mg/L
Lead dis	0.01	NA	mg/L
Zinc dis	NA	5	mg/L
Hardness	NA	NA	mg/L
Arsenic dis	0.01	NA	mg/L
Nitrate	10	NA	mg/L
Selenium	0.05	NA	mg/L
Uranium	0.02	NA	mg/L

P190108037	P190122045	P190205063
ADL Plant	ADL Plant	ADL Plant
January 8, 2019	January 22, 2019	February 5, 2019
79 Water Street	79 Water Street	79 Water Street
7	7	7
7.8	7.9	7.9
133	137	146
40.1	39.5	55.3
0.5280	0.5253	0.4413
71.76	79.31	83.34
0.77	0.78	0.87
0.0170	0.0230.0180	0.0140
<0.0020	<0.0020	<0.0020
1.90	1.93	2.08
<0.0005	<0.0005	<0.0005
0.03	0.03	0.02
14.57	14.26	20.02
10.97	11.58	11.61
0.0001	0.0001	<0.0001
0.0030	0.0030	<0.0020
187	192.5	216.7
0.0004	0.0004	0.0004
5.9	6.2	5.1
0.0002	<0.0002	<0.0002
0.0012	0.0012	0.0012

P190207018	P190207019	P190207020	P190207021
Beth Pizio	Debbie Cameron	Dorothy Kaye	Bob Wiley
February 7, 2019	February 7, 2019	February 7, 2019	February 7, 2019
374 Myrtle St	375 Second Street	234 Duke St	335 Argyle St
4	6	4	4
7.9	7.9	7.9	8.0
151	149	154	149
63.5	50.9	70.1	52.3
0.0682	0.4502	0.3984	0.4120
18.79	77.41	87.00	81.20
0.42	0.86	0.81	0.85
0.0290	0.0270	0.0090	0.0200
<.0020	<.0020	<.0020	<.0020
0.44	2.06	1.99	2.03
0.0005	<.0005	<.0005	<.0005
0.02	0.03	0.03	0.03
93.57	19.20	19.34	19.13
12.2	12.2	10.99	11.9
<0.0001	<0.0001	0.0014	0.0001
0.0130	<0.002	0.0080	0.0230
48.7	201.8	225.4	211.1
0.0004	0.0006	0.0005	0.0005
5.5	5.6	3.7	5.4
<.0002	<0.0002	<.0002	<.0002
0.001	0.0013	0.0008	0.0012

P190207022	P190207023	P190219020	P190219033
Sterling Beaton	Hilcrest Housing Apt. 1	ADL	Sandra Baten
February 7, 2019	February 7, 2019	February 19, 2019	February 19, 2019
341 Argyle St	168 Central St	79 Water Street	377 Notre Dame St
4	4	7	6
8.0	7.9	7.8	7.7
149	151	141	166
52.4	52.7	53.9	125.3
0.4125	0.4179	0.5025	0.7383
80.00	82.70	73.86	99.69
0.84	0.86	0.83	1.19
0.1200	0.0470	0.0130	0.0550
<.0020	<.0020	<.0020	<.0020
2.11	2.03	2.08	3.25
<.0005	<.0005	<0.0005	<.0005
0.03	0.03	0.03	0.02
18.04	18.53	18.92	40.29
12.27	11.97	11.89	15.37
0.0003	0.0001	0.0001	0.0001
0.0340	0.0140	0.0020	0.0020
208.5	214.8	193	262.3
0.0005	0.0005	0.0005	0.0007
5.3	5.3	5.9	4
<.0002	<.0002	<.0002	0.0002
0.0012	0.0012	0.0011	0.0021

P190307052	P190319056	P190403060	P190409055
ADL	ADL	ADL	S7 Well
March 7, 2019	March 19, 2019	April 3, 2019	April 9, 2019
79 Water Street	79 Water Street	79 Water Street	123 Walker Ave
7	7	7	3
8.0	8.0	7.9	7.9
141	152	144	169
51.1	60.5	62.1	209.6
0.5223	0.5009	0.4967	0.6844
78.16	88.53	81.94	137.30
0.87	0.99	0.93	1.28
0.0150	0.0170	0.0180	0.0040
<.002	<.0020	<0.0020	0.003
2.15	2.32	2.12	3.77
<.0005	<.0005	<0.0005	<.0005
0.02	0.02	0.02	0.02
18.01	25.43	20.97	73.16
12.19	13	11.71	19.49
0.0001	0.0001	0.0001	<.0001
0.0020	0.0030	0.0030	0.0020
204	230.6	213.3	358.3
0.0005	0.0004	0.0004	0.0004
6.1	5.4	6.2	3.6
<.0002	<0.0002	<.0002	<.0002
0.0013	0.0012	0.0010	0.0014

Chemistry

P190409056	P190409057	P190409058	P190409059
S1 Well	Wilmot Well Field (#1)	S10 Well	SE4
April 9, 2019	April 9, 2019	April 9, 2019	April 9, 2019
411 North Market Street	855 Read Dr	277 Greenwood Dr	26 Briggs Street
6	8	2	1
7.8	8.0	7.7	7.8
185	119	198	164
143.8	15.3	129.5	120.5
0.7585	0.4179	0.1982	0.2087
114.50	61.93	113.00	97.59
1.32	0.62	1.31	1.15
<.0020	<.0020	0.0210	<.0020
0.002	0.002	0.002	<.0020
3.38	1.37	2.54	2.28
<.0005	<.0005	<.0005	<.0005
0.02	0.03	0.03	0.04
54.28	7.05	53.29	48.79
17.36	10.42	15.73	16.39
0.0001	0.0001	0.0006	<.0001
0.0270	0.0020	0.0380	0.0080
299.8	160.3	292.6	253.1
0.0007	0.0003	0.0002	0.0003
3.3	7.6	2.6	5.2
0.0002	<.0002	<.0002	<.0002
0.0021	0.0005	0.0003	0.0002

Analysis on all City Wells in Operation

P190409060	P190409061	P190409062	P190409063
SE1	St Eleanors (#2)	St Eleanors (#3)	Wilmot Well Field (#2)
April 9, 2019	April 9, 2019	April 9, 2019	April 9, 2019
152 South Drive	80 Bayview Dr	80 Bayview Drive	855 Read Drive
2	2	2	8
7.9	8.0	7.8	7.9
159	151	162	122
72.1	34.9	31.4	15.5
0.3037	0.4697	0.4122	0.4158
90.74	74.24	78.65	63.30
0.79	0.81	0.90	0.62
0.2030	0.0020	<.0020	<.0020
<.0020	<.0020	0.003	<.0020
1.89	1.91	1.91	1.37
<.0005	<.0005	0.0009	<.0005
0.02	0.03	0.02	0.03
19.73	15.08	16.72	7.37
11.08	12.19	12.66	10.4
0.0001	0.0001	<.0001	0.0001
0.0210	0.0120	0.0050	0.0020
234.3	193.2	204.3	163.7
0.0003	0.0007	0.0004	0.0002
3.0	5.8	7.3	7.5
<.0002	<.0002	<.0002	<.0002
0.0006	0.0015	0.0009	0.0005

P190409064	P190409065	P190418042	P190430056
Wilmot Well Field (#3)	Wilmot Well Field (#4)	ADL	ADL
April 9, 2019	April 9, 2019	April 18, 2019	April 30, 2019
855 Read Drive	855 Read Drive	79 Water Street	79 Water Street
8	8	7	7
8.0	7.8	7.8	7.9
119	146	138	116
15.4	21.2	51.6	20.1
0.4081	0.3334	0.4972	0.4475
62.09	72.32	77.37	64.35
0.62	0.69	0.79	0.64
<.0020	<.0020	0.0130	0.0100
0.002	<.0020	<.0020	<.0020
1.37	1.59	1.89	1.43
<.0005	<.0005	<.0005	<.0005
0.03	0.03	0.02	0.03
7.08	10.33	18.60	8.16
10.41	11.8	11.9	10.42
<.0001	<.0001	<.0001	<.0001
0.0030	0.0040	<.0020	0.0020
160.7	187.1	201	166.6
0.0003	0.0002	0.0004	0.0003
7.6	7.3	6.1	7.2
<.0002	<.0002	<.0002	<.0002
0.0004	0.0003	0.0009	0.0006

P190514097	P190528088	P190611119	P190710122
ADL	ADL	ADL	ADL
May 14, 2019	May 28, 2019	June 11, 2019	July 10, 2019
79 Water Street	79 Water Street	79 Water Street	79 Water Street
7	7	7	7
7.9	7.9	8.4	7.6
126	139	160	150
43.7	40.7	111.0	108.7
0.6736	0.4516	0.5937	0.6981
65.41	69.75	90.95	91.52
0.88	0.83	1.28	1.15
0.0110	0.0210	0.0230	0.0160
<.0020	<.0020	<.0020	<.0020
2.19	1.91	3.18	2.97
<.0005	<.0005	<.0005	<.0005
0.02	0.03	0.02	0.02
15.62	16.14	39.87	34.62
10.01	11.37	15.58	14.31
<.0001	0.0001	<.0001	0.0001
<.0020	0.0020	0.0030	0.0020
172.3	182	240.2	240.7
0.0004	0.0004	0.0005	0.0005
5.4	6.2	4.5	4.8
<.0002	<.0002	<.0002	<.0002
0.0016	0.0011	0.0017	0.0019

P190723085	P190806057	P19082096	P190903041
ADL	ADL	ADL	ADL
July 23, 2019	August 6, 2019	August 20, 2019	September 3, 2019
79 Water Street	79 Water Street	79 Water Street	79 Water Street
7	7	7	7
7.7	7.6	7.7	8.0
152	155	138	147
64.2	105.3	48.5	66.0
0.6368	0.6950	0.5793	0.6217
71.84	90.67	69.17	79.70
0.92	1.08	0.85	0.95
0.0280	0.0200	0.0280	0.0220
<.0020	<.0020	<.0020	<.0020
2.39	2.90	2.21	2.38
<.0005	<.0005	<.0005	<.0005
0.02	0.02	0.03	0.02
22.33	32.92	19.15	24.21
12.01	14.24	11.98	12.28
0.0002	0.0002	0.0002	0.0001
0.0030	0.0020	0.0040	0.0030
189.2	238.3	181.8	208.8
0.0005	0.0005	0.0005	0.0005
5.2	4.6	6.5	5.3
<.0002	<.0002	<.0002	<.0002
0.0018	0.0020	0.0013	0.0016

P190919094	P191001093	P191015045	P191029051
ADL	ADL	ADL	ADL
September 19, 2019	October 1, 2019	October 15, 2019	October 29, 2019
79 Water Street	79 Water Street	79 Water Street	79 Water Street
7	7	7	7
7.8	7.8	7.8	7.6
129	139	140	144
50.0	39.7	45.0	57.2
0.6541	0.6541	0.6504	0.5822
64.75	69.39	66.93	74.90
0.80	0.95	0.92	0.92
0.0170	0.0180	0.0200	0.0260
<.0020	<.0020	<.0020	<.0020
2.18	2.36	2.33	2.45
<.0005	<.0005	<.0005	<.0005
0.02	0.03	0.02	0.02
17.65	16.29	16.42	20.42
10	9.86	10.72	12.22
0.0001	<.0001	0.0001	0.0001
0.0030	0.0020	0.0040	0.0040
170.6	182.9	176.7	197.1
0.0004	0.0004	0.0005	0.0005
5.0	4.7	4.9	5.6
<.0002	<.0002	<.0002	<.0002
0.0014	0.0021	0.0020	0.0016

P191119027	P191119028	P191119029	P191119030
S1 Well	Linkletter Well #1	Linkletter Well #2	Linkletter Well #3
November 19, 2019	November 19, 2019	November 19, 2019	November 19, 2019
411 North Market	80 Bayview Dr	80 Bayview Dr	80 Bayview Dr
6	2	2	2
	7.9	7.9	7.9
	150	155	147
	71.3	35.1	32.1
	0.2560	0.3888	0.6693
	82.46	72.43	70.52
	0.89	0.87	0.97
	<.0020	<.0020	<.0020
	<.0020	<.0020	<.0020
	1.77	1.96	2.39
	<.0005	<.0005	<.0005
	0.04	0.03	0.02
	25.20	15.90	14.26
	12.66	11.85	11.86
	<.0001	<.0001	<.0001
	<.0020	<.0020	<.0020
	213.2	188.9	185.9
	0.0004	0.0005	0.0008
	3.1	4.9	6.2
	<.0002	<.0002	<.0002
	0.0005	0.0010	0.0024

Chemistry Analysis on all City Wells In Operation

P191119031	P191119032	P191119033	P191119034
Briggs St Well	SE-1 Well	Greenwood Dr Well	Sears Well
November 19, 2019	November 19, 2019	November 19, 2019	November 19, 2019
26 Briggs St	152 South Dr	277 Greenwood Dr	123 Walker Ave
1	2	2	3
7.7	7.8	7.6	7.7
150	165	194	165
130.3	78.9	119.7	233.9
0.2200	0.2715	0.1566	0.7169
93.03	88.99	95.80	125.30
1.24	0.87	1.50	1.35
<.0020	0.0210	<.0020	0.0020
<.0020	<.0020	<.0020	<.0020
2.21	1.95	2.54	3.84
<.0005	<.0005	<.0005	<.0005
0.04	0.02	0.03	0.02
51.88	21.16	50.59	75.79
16.28	10.79	14.77	19.98
<.0001	0.0002	0.0001	<.0001
0.0070	0.0250	0.0360	0.0020
241.4	230.2	249.7	328.7
0.0003	0.0003	0.0002	0.0004
5.4	2.7	2.5	3.3
<.0002	<.0002	<.0002	<.0002
0.0002	0.0005	0.0002	0.0015

P191119035	P191110936	P191119037	P191119038
Wilmot Well #1	Wilmot Well #2	Wilmot Well #3	Wilmot Well #4
November 19, 2019	November 19, 2019	November 13, 2019	November 19, 2019
855 Read Dr	855 Read Dr	855 Read Dr	855 Read Dr
8	8	8	8
7.8	7.8	7.8	8.0
116	145	116	136
16.7	14.8	16.8	20.7
0.4079	0.3367	0.4087	0.3572
63.31	64.69	60.99	68.93
0.68	0.76	0.64	0.74
<.0020	<.0020	<.0020	<.0020
<.0020	<.0020	<.0020	<.0020
1.34	1.64	1.49	1.71
<.0005	<.0005	<.0005	<.0005
0.03	0.04	0.03	0.03
7.70	8.71	7.15	10.97
10.16	11.84	10.02	10.59
0.0001	<.0001	<.0001	<.0001
<.0020	<.0020	<.0020	0.0040
163.6	168.3	158.4	179.2
0.0002	0.0003	0.0002	0.0003
8.0	4.6	8.6	7.1
<.0002	<.0002	<.0002	<.0002
0.0004	0.0006	0.0004	0.0005

P191126045	P191210076	P191227029
ADL	ADL	ADL
November 26, 2019	December 10, 2019	December 27, 2019
79 Water Street	79 Water Street	79 Water Street
7	7	7
8.1	7.6	7.7
142	155	139
61.7	69.8	60.0
0.5309	0.4390	0.5402
76.03	79.26	74.48
0.97	0.93	0.89
0.0230	0.0170	0.0160
<.0020	<.0020	<.0020
2.36	2.28	2.34
<.0005	<.0005	<.0005
0.02	0.03	0.02
23.31	26.17	21.65
11.58	13.83	12.49
0.0001	<.0001	<.0001
0.0060	0.0020	0.0020
199.6	207.3	195.6
0.0004	0.0004	0.0004
5.5	5.6	6.0
<.0002	<.0002	<.0002
0.0014	0.0011	0.0012

Summerside

Free Chlorine Residual - Should be a minimum of 0.1 at all locations at all times
 E. Coli. Bacteria Colony Count - required to be 0. If non-zero count is present water is deemed unfit for human consumption.
 Total Coliforms Bacteria Colony Count - If 10 or less bacteria is present but not sufficient to regard water unfit for drinking. Water must be re-tested.
 Background Growth Bacteria Colony Count - Must be below 200 at all times

		8-Jan-19							
No.	Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli.	Background Growth
No. 1	P190108032	St. Eleanor's Community Center (Kitchen Sink)	08-Jan-19	1 West Drive	1	0.69	0	0	0
No. 2	P190108033	Hilsley's Feed Store (Bathroom Sink)	08-Jan-19	61 Mill Cr.	2	0.56	0	0	0
No. 3	P190108034	Summerset Manor (Meter Room Sink)	08-Jan-19	15 Frank Mellich St	3	0.51	0	0	0
No. 4	P190108035	Lions Club Senior Housing (Common Room Sink)	08-Jan-19	326 Brophy St	4	0.40	0	0	0
No. 5	P190108036	Summerside Firehall (Station #1)	08-Jan-19	251 Foundry Street	6	0.66	0	0	0
No. 6	P190108037	ADL Plant (Maintenance Room Sink)	08-Jan-19	79 Water street	7	0.60	0	0	0
No. 7	P190108038	Bens Bakery Outlet Store (Bathroom Sink)	08-Jan-19	688 Water Street East	7	0.53	0	0	0
No. 8	P190108039	Tim Hortons Esso (Bakery Sink)	08-Jan-19	820 Water Street East	6	0.68	0	0	0
No. 9	P190108040	S7 Well (Well Head)	08-Jan-19	123 Walker Ave	6	0.57	0	0	0
No. 10	P190108041	S1 Well (Well Head)	08-Jan-19	411 Northmarket St	6	0.79	0	0	0
No. 11	P190108042	Wilmot Well Field (Well # 3 @ Pipe Gallery)	08-Jan-19	855 Read Drive	8	0.81	0	0	0
No. 12	P190108043	S10 Well (Well Head)	08-Jan-19	277 Greenwood Dr	2	0.70	0	0	0
No. 13	P190108044	SE4 (Well Head)	08-Jan-19	26 Briggs St	1	0.67	0	0	0
No. 14	P190108045	SE1 (Well Head)	08-Jan-19	152 South Dr	1	0.69	0	0	0
No. 15	P190108047	St Eleanor's Well Field (Well #1)	08-Jan-19	80 Bayview Dr	2	0.63	0	0	0
No. 16	P190108048	St Eleanor's Well Field (Well #2)	08-Jan-19	80 Bayview Dr	2	0.54	0	0	0
No. 17	P190108049	St Eleanor's Well Field (Well #3)	08-Jan-19	80 Bayview Dr	2	0.77	0	0	0
No. 18	P190108050	Bernard's Quick Mart (Laundry Sink)	08-Jan-19	126 Bayview Dr	1	0.46	0	0	0
No. 19	P190108051	Summerside Wastewater Treatment Plant	08-Jan-19	15 Seaweed Rd	2	0.63	0	0	0

		22-Jan-19							
No.	Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli.	Background Growth
No. 20	P190122040	St. Eleanor's Community Center (Kitchen Sink)	22-Jan-19	1 West Drive	1	0.57	0	0	0
No. 21	P190122041	Hilsley's Feed Store (Bathroom Sink)	22-Jan-19	61 Mill Cr.	2	0.49	0	0	0
No. 22	P190122042	Summerset Manor (Meter Room Sink)	22-Jan-19	15 Frank Mellich St	3	0.44	0	0	0
No. 23	P190122043	Lions Club Senior Housing (Common Room Sink)	22-Jan-19	326 Brophy St	4	0.58	0	0	0
No. 24	P190122044	Summerside Firehall (Station #1)	22-Jan-19	251 Foundry Street	6	0.54	0	0	0
No. 25	P190122045	ADL Plant (Maintenance Room Sink)	22-Jan-19	79 Water street	7	0.60	0	0	0
No. 26	P190122046	Bens Bakery Outlet Store (Bathroom Sink)	22-Jan-19	688 Water Street East	7	0.51	0	0	0
No. 27	P190122047	Tim Hortons Esso (Bakery Sink)	22-Jan-19	820 Water Street East	6	0.55	0	0	0
No. 28	P190122048	S7 Well (Well Head)	22-Jan-19	123 Walker Ave	3	0.72	0	0	0
No. 29	P190122049	S1 Well (Well Head)	22-Jan-19	411 Northmarket St	6	0.87	0	0	0
No. 30	P190122050	Wilmot Well Field (Well # 3 @ Pipe Gallery)	22-Jan-19	855 Read Drive	8	0.81	0	0	0
No. 31	P190122051	S10 Well (Well Head)	22-Jan-19	277 Greenwood Dr	2	0.76	0	0	0
No. 32	P190122052	SE1 (Well Head)	22-Jan-19	152 South Dr	2	0.68	0	0	0
No. 33	P190122053	St Eleanor's Well Field (Well #1)	22-Jan-19	80 Bayview Dr	2	0.63	0	0	0
No. 34	P190122054	St Eleanor's Well Field (Well #2)	22-Jan-19	80 Bayview Dr	2	0.49	0	0	0
No. 35	P190122055	St Eleanor's Well Field (Well #3)	22-Jan-19	80 Bayview Dr	2	0.67	>80	0	0
No. 36	P190122056	Bernard's Quick Mart (Laundry Sink)	22-Jan-19	126 Bayview Dr	1	0.38	0	0	0
No. 37	P190122057	Summerside Wastewater Treatment Plant	22-Jan-19	15 Seaweed Rd	2	0.45	0	0	0

		24-Jan-19							
No.	Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli.	Background Growth
No. 38	P190124014	St Eleanor's Well Field (Well #2) Resample	24-Jan-19	80 Bayview Dr	2	0.6	0	0	0
No. 39	P190124015	St Eleanor's Well Field (Well #3) Resample	24-Jan-19	80 Bayview Dr	2	0.69	31	0	0

		29-Jan-19							
No.	Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli.	Background Growth
No. 40	P190129029	St Eleanor's Well Field (Well #3) Resample	29-Jan-19	80 Bayview Dr	2	0.70	0	0	0

		5-Feb-19							
No.	Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli.	Background Growth
No. 41	P190205058	St. Eleanor's Community Center (Kitchen Sink)	05-Feb-19	1 West Drive	1	0.53	0	0	0
No. 42	P190205059	Hilsley's Feed Store (Bathroom Sink)	05-Feb-19	61 Mill Cr.	2	0.65	0	0	0
No. 43	P190205060	Summerset Manor (Meter Room Sink)	05-Feb-19	15 Frank Mellich St	3	0.76	0	0	0
No. 44	P190205061	Lions Club Senior Housing (Common Room Sink)	05-Feb-19	326 Brophy St	4	0.45	0	0	0
No. 45	P190205062	Summerside Firehall (Station #1)	05-Feb-19	251 Foundry Street	6	0.35	0	0	0
No. 46	P190205063	ADL Plant (Maintenance Room Sink)	05-Feb-19	79 Water street	7	0.37	0	0	0
No. 47	P190205064	Bens Bakery Outlet Store (Bathroom Sink)	05-Feb-19	688 Water Street East	7	0.47	0	0	0
No. 48	P190205065	Tim Hortons Esso (Bakery Sink)	05-Feb-19	820 Water Street East	6	0.54	0	0	0
No. 49	P190205066	S7 Well (Well Head)	05-Feb-19	123 Walker Ave	3	0.55	0	0	0
No. 50	P190205067	S1 Well (Well Head)	05-Feb-19	411 Northmarket St	6	0.88	0	0	0
No. 51	P190205068	Wilmot Well Field (Well # 3 @ Pipe Gallery)	05-Feb-19	855 Read Drive	8	0.87	0	0	0
No. 52	P190205069	S10 Well (Well Head)	05-Feb-19	277 Greenwood Dr	2	0.50	0	0	0
No. 53	P190205070	SE4 (Well Head)	05-Feb-19	26 Briggs St	1	0.60	0	0	0
No. 54	P190205071	SE1 (Well Head)	05-Feb-19	152 South Dr	2	0.62	0	0	0
No. 55	P190205072	Summerset Manor	05-Feb-19	15 Frank Mellich St	3	0.49	0	0	0
No. 56	P190205073	St Eleanor's Well Field (Well #1)	05-Feb-19	80 Bayview Dr	2	0.75	1	0	0
No. 57	P190205074	St Eleanor's Well Field (Well #2)	05-Feb-19	80 Bayview Dr	2	0.67	0	0	0
No. 58	P190205075	St Eleanor's Well Field (Well #3)	05-Feb-19	80 Bayview Dr	2	0.50	8	0	0
No. 59	P190205076	Bernard's Quick Mart (Laundry Sink)	05-Feb-19	126 Bayview Dr	1	0.63	0	0	0
No. 59	P190205077	Summerside Wastewater Treatment Plant	05-Feb-19	15 Seaweed Rd	2	0.54	0	0	0

		7-Feb-19							
No.	Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli.	Background Growth
No. 60	P190207018	Beth Pizio (Kitchen Sink)	07-Feb-19	374 Myrtle St	4	0.02	3	0	0
No. 61	P190207020	Dorothy Kaye (Kitchen Sink)	07-Feb-19	234 Duke St	4	0.22	0	0	0
No. 62	P190207021	Bob Wiley (Kitchen Sink)	07-Feb-19	335 Argyle	4	0.42	0	0	0
No. 63	P190207022	Sterling Beaton (Kitchen Sink)	07-Feb-19	341 Argyle St	4	0.49	0	0	0
No. 64	P190207023	Hilcrest Housing (Kitchen Sink)	07-Feb-19	168 Central St Apt 1	4	0.54	0	0	0
No. 65	P190207024	St Eleanor's Well Field (Well 1) Resample	07-Feb-19	80 Bayview Dr	2	0.69	36	0	0
No. 66	P190207025	St Eleanor's Well Field (Well 3) Resample	07-Feb-19	80 Bayview Dr	2	0.77	0	0	0

		9-Feb-19							
No.	Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coll.	Background Growth
67	P19020901	N/A (Kitchen Sink)	09-Feb-19	341 Second St	6	0.34	0	0	0
68	P19020902	N/A (Kitchen Sink)	09-Feb-19	342 Second St	6	0.43	0	0	0
69	P19020903	Debbie Cameron (Bathroom Sink)	09-Feb-19	375 Second St	6	0.29	0	0	0
70	P19020904	N/A (Bathroom Sink)	09-Feb-19	397 Water St	6	0.48	0	0	0
71	P19020905	S-1 Well (Well Head)	09-Feb-19	411 North Market St	6	0.89	0	0	0
72	P19020906	SE-1 Well (Well Head)	09-Feb-19	152 South Dr	1	0.58	0	0	0
73	P19020907	St Eleanor's Well Field (Well 3) Resample	09-Feb-19	80 Bayview Dr	2	0.66	5	0	0
74	P19020908	St Eleanor's Well Field (Well 1) Resample	09-Feb-19	80 Bayview Dr	2	0.72	0	0	0

		19-Feb-19							
No.	Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coll.	Background Growth
75	P190219015	St. Eleanor's Community Center (Kitchen Sink)	19-Feb-19	1 West Drive	1	0.77	0	0	0
76	P190219016	Illsley's Feed Store (Bathroom Sink)	19-Feb-19	61 Mill Cr.	2	0.43	0	0	0
77	P190219017	Summerset Manor (Meter Room Sink)	19-Feb-19	15 Frank Mellich St	3	0.71	0	0	0
78	P190219018	Lions Club Senior Housing (Common Room Sink)	19-Feb-19	326 Brophy St	4	0.30	0	0	0
79	P190219019	Summerside Firehall (Station #1)	19-Feb-19	251 Foundry Street	6	0.33	0	0	0
80	P190219020	ADL Plant (Maintenance Room Sink)	19-Feb-19	79 Water street	7	0.43	0	0	0
81	P190219021	Bens Bakery Outlet Store (Bathroom Sink)	19-Feb-19	686 Water Street East	7	0.58	0	0	0
82	P190219022	Tim Hortons Esso (Bakery Sink)	19-Feb-19	820 Water Street East	8	0.51	0	0	0
83	P190219023	S7 Well (Well Head)	19-Feb-19	123 Walker Ave	3	0.75	0	0	0
84	P190219024	S1 Well (Well Head)	19-Feb-19	411 Northmarket St	6	0.91	0	0	0
85	P190219025	Wilmot Well Field (Well # 3 @ Pipe Gallery)	19-Feb-19	855 Read Drive	8	0.80	0	0	0
86	P190219026	S10 Well (Well Head)	19-Feb-19	277 Greenwood Dr	2	0.71	0	0	0
87	P190219027	SE4 (Well Head)	19-Feb-19	26 Briggs St	1	0.01	0	0	0
88	P190219028	SE1 (Well Head)	19-Feb-19	152 South Dr	2	0.93	0	0	0
89	P190219029	St Eleanor's Well Field (Well #2)	19-Feb-19	80 Bayview Dr	2	0.64	3	0	0
90	P190219030	St Eleanor's Well Field (Well #3)	19-Feb-19	80 Bayview Dr	2	0.73	0	0	0
91	P190219031	Bernard's Quick Mart (Laundry Sink)	19-Feb-19	126 Bayview Dr	1	0.31	0	0	0
92	P190219032	Summerside Wastewater Treatment Plant	19-Feb-19	15 Seaweed Rd	2	0.49	0	0	0
93	P190219033	Sandra Baten	18-Feb-19	377 Notre Dame St	6	0.62	0	0	0

		7-Mar-19							
No.	Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coll.	Background Growth
94	P190307047	St. Eleanor's Community Center (Kitchen Sink)	07-Mar-19	1 West Drive	1	0.67	0	0	0
95	P190307048	Illsley's Feed Store (Bathroom Sink)	07-Mar-19	61 Mill Cr.	2	0.60	0	0	0
96	P190307049	Summerset Manor (Meter Room Sink)	07-Mar-19	15 Frank Mellich St	3	0.52	0	0	0
97	P190307050	Lions Club Senior Housing (Common Room Sink)	07-Mar-19	326 Brophy St	4	0.52	0	0	0
98	P190307051	Summerside Firehall (Station #1)	07-Mar-19	251 Foundry Street	6	0.42	0	0	0
99	P190307052	ADL Plant (Maintenance Room Sink)	07-Mar-19	79 Water street	7	0.59	0	0	0
100	P190307053	Bens Bakery Outlet Store (Bathroom Sink)	07-Mar-19	686 Water Street East	7	0.43	0	0	0
101	P190307054	Tim Hortons Esso (Bakery Sink)	07-Mar-19	820 Water Street East	8	0.61	0	0	0
102	P190307055	S7 Well (Well Head)	07-Mar-19	123 Walker Ave	3	0.85	0	0	0
103	P190307056	S1 Well (Well Head)	07-Mar-19	411 Northmarket St	6	0.88	0	0	0
104	P190307057	Wilmot Well Field (Well # 3 @ Pipe Gallery)	07-Mar-19	855 Read Drive	8	0.66	0	0	0
105	P190307058	S10 Well (Well Head)	07-Mar-19	277 Greenwood Dr	2	0.68	0	0	0
106	P190307059	SE4 (Well Head)	07-Mar-19	26 Briggs St	1	0.88	0	0	0
107	P190307060	SE1 (Well Head)	07-Mar-19	152 South Dr	2	0.96	0	0	0
108	P190307061	Summerset Manor	07-Mar-19	15 Frank Mellich St	3	0.28	0	0	0
109	P190307062	St Eleanor's Well Field (Well #2)	07-Mar-19	80 Bayview Dr	2	0.62	>80	0	0
110	P190307063	St Eleanor's Well Field (Well #3)	07-Mar-19	80 Bayview Dr	2	0.69	0	0	0
111	P190307064	Bernard's Quick Mart (Laundry Sink)	07-Mar-19	126 Bayview Dr	1	0.54	0	0	0
112	P190307065	Summerside Wastewater Treatment Plant	07-Mar-19	15 Seaweed Rd	2	0.51	0	0	0

		11-Mar-19							
No.	Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coll.	Background Growth
113	P190307062	St Eleanor's Well Field (Well #2)	11-Mar-19	80 Bayview Dr	2	0.68	0	0	0
114	P190307063	St Eleanor's Well Field (Valve Before Chlorination)	11-Mar-19	80 Bayview Dr	2	N/A	14	0	0

		13-Mar-19							
No.	Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coll.	Background Growth
115	P190314008	St Eleanor's Well Field (Valve Before Chlorination)Resample	13-Mar-19	80 Bayview Dr	2	N/A	0	0	0

		19-Mar-19							
No.	Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coll.	Background Growth
116	P190319051	St. Eleanor's Community Center (Kitchen Sink)	19-Mar-19	1 West Drive	1	0.62	0	0	0
117	P190319052	Illsley's Feed Store (Bathroom Sink)	19-Mar-19	61 Mill Cr.	2	0.55	0	0	0
118	P190319053	Summerset Manor (Meter Room Sink)	19-Mar-19	15 Frank Mellich St	3	0.51	0	0	0
119	P190319054	Lions Club Senior Housing (Common Room Sink)	19-Mar-19	326 Brophy St	4	0.34	0	0	0
120	P190319055	Summerside Firehall (Station #1)	19-Mar-19	251 Foundry Street	6	0.43	0	0	0
121	P190319056	ADL Plant (Maintenance Room Sink)	19-Mar-19	79 Water street	7	0.60	0	0	0
122	P190319057	Bens Bakery Outlet Store (Bathroom Sink)	19-Mar-19	686 Water Street East	7	0.63	0	0	0
123	P190319058	Tim Hortons Esso (Bakery Sink)	19-Mar-19	820 Water Street East	8	0.72	0	0	0
124	P190319059	S7 Well (Well Head)	19-Mar-19	123 Walker Ave	3	0.95	0	0	0
125	P190319060	S1 Well (Well Head)	19-Mar-19	411 Northmarket St	6	0.91	0	0	0
126	P190319061	Wilmot Well Field (Well # 3 @ Pipe Gallery)	19-Mar-19	855 Read Drive	8	0.85	0	0	0
127	P190319062	S10 Well (Well Head)	19-Mar-19	277 Greenwood Dr	2	0.70	0	0	0
128	P190319063	SE4 (Well Head)	19-Mar-19	26 Briggs St	1	0.66	0	0	0
129	P190319064	SE1 (Well Head)	19-Mar-19	152 South Dr	2	0.61	0	0	0
130	P190319065	St Eleanor's Well Field (Well #2)	19-Mar-19	80 Bayview Dr	2	0.68	59	0	0
131	P190319066	St Eleanor's Well Field (Well #3)	19-Mar-19	80 Bayview Dr	2	0.77	2	0	0
132	P190319067	Bernard's Quick Mart (Laundry Sink)	19-Mar-19	126 Bayview Dr	1	0.59	0	0	0
133	P190319068	Summerside Wastewater Treatment Plant	19-Mar-19	15 Seaweed Rd	2	0.52	0	0	0

		21-Mar-19							
No.	Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coll.	Background Growth
134	P190322010	St Eleanor's Well Field (Well #3) (Resample)	21-Mar-19	80 Bayview Dr	2	0.78	42	0	0
135	P190322011	St Eleanor's Well Field (Well #2) (Resample)	21-Mar-19	80 Bayview Dr	2	0.65	2	0	0

		3-Apr-19							
No.	Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coll.	Background Growth
136	P190403055	St. Eleanor's Community Center (Kitchen Sink)	03-Apr-19	1 West Drive	1	0.78	0	0	0
137	P190403056	Illsley's Feed Store (Bathroom Sink)	03-Apr-19	61 Mill Cr.	2	0.49	0	0	0
138	P190403057	Summerset Manor (Meter Room Sink)	03-Apr-19	15 Frank Mellich St	3	0.53	0	0	0
139	P190403058	Lions Club Senior Housing (Common Room Sink)	03-Apr-19	326 Brophy St	4	0.62	0	0	0
140	P190403059	Summerside Firehall (Station #1)	03-Apr-19	251 Foundry Street	6	0.53	0	0	0
141	P190403060	ADL Plant (Maintenance Room Sink)	03-Apr-19	79 Water street	7	0.61	0	0	0
142	P190403061	Bens Bakery Outlet Store (Bathroom Sink)	03-Apr-19	686 Water Street East	7	0.77	0	0	1
143	P190403062	Tim Hortons Esso (Bakery Sink)	03-Apr-19	820 Water Street East	8	0.56	0	0	0
144	P190403063	S7 Well (Well Head)	03-Apr-19	123 Walker Ave	3	0.87	0	0	0
145	P190403064	S1 Well (Well Head)	03-Apr-19	411 Northmarket St	6	0.88	0	0	0
146	P190403065	Wilmot Well Field (Well # 3 @ Pipe Gallery)	03-Apr-19	855 Read Drive	8	0.80	0	0	0
147	P190403066	S10 Well (Well Head)	03-Apr-19	277 Greenwood Dr	2	0.79	0	0	0

No.	148	P190403067	SE4 (Well Head)	03-Apr-19	26 Briggs St	1	0.60	0	0	0
No.	149	P190403068	SE1 (Well Head)	03-Apr-19	152 South Dr	2	0.81	0	0	0
No.	150	P190403070	St Eleanor's Well Field (Well #2)	03-Apr-19	80 Bayview Dr	2	0.71	0	0	0
No.	151	P190403071	Bernard's Quick Mart (Laundry Sink)	03-Apr-19	126 Bayview Dr	1	0.69	0	0	0
No.	152	P190403072	Summerside Wastewater Treatment Plant	03-Apr-19	15 Seaweed Rd	2	0.53	0	0	0
No.	153	P190403073	Summerside Electric Building	03-Apr-19	94 Ottawa St	7	0.41	0	0	0

18-Apr-19										
		Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth	
No.	154	P190418037	St. Eleanor's Community Center (Kitchen Sink)	18-Apr-19	1 West Drive	1	0.77	0	0	0
No.	155	P190418038	Illsley's Feed Store (Bathroom Sink)	18-Apr-19	61 Mill Cr.	2	0.73	0	0	0
No.	156	P190418039	Summerset Manor (Meter Room Sink)	18-Apr-19	15 Frank Mellish St	3	0.59	0	0	0
No.	157	P190418040	Lions Club Senior Housing (Common Room Sink)	18-Apr-19	326 Brophy St	4	0.93	0	0	0
No.	158	P190418041	Summerside Firehall (Station #1)	18-Apr-19	251 Foundry Street	6	0.50	0	0	0
No.	159	P190418042	ADL Plant (Maintenance Room Sink)	18-Apr-19	79 Water street	7	0.53	0	0	0
No.	160	P190418043	Bens Bakery Outlet Store (Bathroom Sink)	18-Apr-19	686 Water Street East	7	0.60	0	0	0
No.	161	P190418044	Tim Hortons Esso (Bakery Sink)	18-Apr-19	820 Water Street East	8	0.62	0	0	0
No.	162	P190418045	S7 Well (Well Head)	18-Apr-19	123 Walker Ave	3	0.85	0	0	0
No.	163	P190418046	S1 Well (Well Head)	18-Apr-19	411 Northmarket St	6	0.92	0	0	0
No.	164	P190418047	Wilmot Well Field (Well # 3 @ Pipe Gallery)	18-Apr-19	855 Read Drive	8	0.82	0	0	0
No.	165	P190418048	S10 Well (Well Head)	18-Apr-19	277 Greenwood Dr	2	0.61	0	0	0
No.	166	P190418049	SE4 (Well Head)	18-Apr-19	26 Briggs St	1	0.81	0	0	0
No.	167	P190418050	SE1 (Well Head)	18-Apr-19	152 South Dr	2	0.69	0	0	0
No.	168	P190418052	St Eleanor's Well Field (Well #2)	18-Apr-19	80 Bayview Dr	2	0.79	0	0	0
No.	169	P190418053	Bernard's Quick Mart (Laundry Sink)	18-Apr-19	126 Bayview Dr	1	0.56	0	0	0
No.	170	P190418054	Summerside Wastewater Treatment Plant	18-Apr-19	15 Seaweed Rd	2	0.72	0	0	0

30-Apr-19										
		Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth	
No.	171	P190430051	St. Eleanor's Community Center (Kitchen Sink)	30-Apr-19	1 West Drive	1	0.65	0	0	0
No.	172	P190430052	Illsley's Feed Store (Bathroom Sink)	30-Apr-19	61 Mill Cr.	2	0.68	0	0	0
No.	173	P190430053	Summerset Manor (Meter Room Sink)	30-Apr-19	15 Frank Mellish St	3	0.83	0	0	0
No.	174	P190430054	Lions Club Senior Housing (Common Room Sink)	30-Apr-19	326 Brophy St	4	0.81	0	0	0
No.	175	P190430055	Summerside Firehall (Station #1)	30-Apr-19	251 Foundry Street	6	0.54	0	0	0
No.	176	P190430056	ADL Plant (Maintenance Room Sink)	30-Apr-19	79 Water street	7	0.57	0	0	0
No.	177	P190430057	Bens Bakery Outlet Store (Bathroom Sink)	30-Apr-19	686 Water Street East	7	0.69	0	0	0
No.	178	P190430058	Tim Hortons Esso (Bakery Sink)	30-Apr-19	820 Water Street East	8	0.71	0	0	0
No.	179	P190430059	S7 Well (Well Head)	30-Apr-19	123 Walker Ave	3	0.78	0	0	0
No.	180	P190430060	S1 Well (Well Head)	30-Apr-19	411 Northmarket St	6	0.99	0	0	0
No.	181	P190430061	Wilmot Well Field (Well # 4 @ Pipe Gallery)	30-Apr-19	855 Read Drive	8	0.87	6	0	0
No.	182	P190430062	S10 Well (Well Head)	30-Apr-19	277 Greenwood Dr	2	0.94	0	0	0
No.	183	P190430063	SE4 (Well Head)	30-Apr-19	26 Briggs St	1	0.86	0	0	0
No.	184	P190430064	SE1 (Well Head)	30-Apr-19	152 South Dr	2	0.66	0	0	0
No.	185	P190430065	St Eleanor's Well Field (Well #2)	30-Apr-19	80 Bayview Dr	2	0.77	27	0	0
No.	186	P190430066	Bernard's Quick Mart (Laundry Sink)	30-Apr-19	126 Bayview Dr	1	0.72	0	0	0
No.	187	P190430067	Summerside Wastewater Treatment Plant	30-Apr-19	15 Seaweed Rd	2	0.71	0	0	0
No.	188	P190430068	Arsenault's Fish Mart	30-Apr-19	246 Heather Moyses Dr	6	0.55	0	0	0

13-May-19										
		Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth
No.	189	P190514007	St. Eleanor's Well Field (Well #3)	13-May-19	80 Bayview Dr	2	0.53	0	0	0

14-May-19										
		Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth
No.	190	P190514092	St. Eleanor's Community Center (Kitchen Sink)	14-May-19	1 West Drive	1	0.66	0	0	0
No.	191	P190514093	Illsley's Feed Store (Bathroom Sink)	14-May-19	61 Mill Cr.	2	0.76	0	0	0
No.	192	P190514094	Summerset Manor (Meter Room)	14-May-19	15 Frank Mellish St	3	0.52	0	0	0
No.	193	P190514095	Lions Club Senior Housing (Common Room Sink)	14-May-19	326 Brophy St	4	0.69	0	0	0
No.	194	P190514096	Summerside Firehall (Station #1)	14-May-19	251 Foundry Street	6	0.70	0	0	0
No.	195	P190514097	ADL Plant (Maintenance Room Sink)	14-May-19	79 Water street	7	0.51	0	0	0
No.	196	P190514098	Bens Bakery Outlet Store (Bathroom Sink)	14-May-19	686 Water Street East	7	0.63	0	0	0
No.	197	P190514099	Tim Hortons Esso (Bakery Sink)	14-May-19	820 Water Street East	8	0.69	0	0	0
No.	198	P190514100	S7 Well (Well Head)	14-May-19	123 Walker Ave	3	0.73	0	0	0
No.	199	P190514101	S1 Well (Well Head)	14-May-19	411 Northmarket St	6	0.87	0	0	0
No.	200	P190514102	Wilmot Well Field (Well # 3 @ Pipe Gallery)	14-May-19	855 Read Drive	8	0.68	0	0	0
No.	201	P190514103	S10 Well (Well Head)	14-May-19	277 Greenwood Dr	2	0.96	0	0	0
No.	202	P190514104	SE4 (Well Head)	14-May-19	26 Briggs St	1	0.69	0	0	0
No.	203	P190514105	SE1 (Well Head)	14-May-19	152 South Dr	2	0.71	0	0	0
No.	204	P190514106	Summerset Manor (Kitchen Sink)	14-May-19	15 Frank Mellish St	3	0.55	0	0	0
No.	205	P190514107	St Eleanor's Well Field (Well #2)	14-May-19	80 Bayview Dr	2	0.73	0	0	0
No.	206	P190514109	Bernard's Quick Mart (Laundry Sink)	14-May-19	126 Bayview Dr	1	0.68	0	0	0
No.	207	P190514110	Summerside Wastewater Treatment Plant	14-May-19	15 Seaweed Rd	2	0.57	0	0	0

28-May-19										
		Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth
No.	208	P190528083	St. Eleanor's Community Center (Kitchen Sink)	28-May-19	1 West Drive	1	0.81	0	0	0
No.	209	P190528084	Illsley's Feed Store (Bathroom Sink)	28-May-19	61 Mill Cr.	2	0.66	0	0	0
No.	210	P190528085	Summerset Manor (Meter Room Sink)	28-May-19	15 Frank Mellish St	3	0.60	0	0	0
No.	211	P190528086	Lions Club Senior Housing (Common Room Sink)	28-May-19	326 Brophy St	4	0.76	0	0	0
No.	212	P190528087	Summerside Firehall (Station #1)	28-May-19	251 Foundry Street	6	0.34	0	0	0
No.	213	P190528088	ADL Plant (Maintenance Room Sink)	28-May-19	79 Water street	7	0.61	0	0	0
No.	214	P190528089	Bens Bakery Outlet Store (Bathroom Sink)	28-May-19	686 Water Street East	7	0.67	0	0	0
No.	215	P190528090	Tim Hortons Esso (Bakery Sink)	28-May-19	820 Water Street East	8	0.69	0	0	0
No.	216	P190528091	S7 Well (Well Head)	28-May-19	123 Walker Ave	3	0.76	0	0	0
No.	217	P190528092	S1 Well (Well Head)	28-May-19	411 Northmarket St	6	0.80	0	0	0
No.	218	P190528093	Wilmot Well Field (Well # 3 @ Pipe Gallery)	28-May-19	855 Read Drive	8	0.83	0	0	0
No.	219	P190528094	S10 Well (Well Head)	28-May-19	277 Greenwood Dr	2	0.69	0	0	0
No.	220	P190528095	SE4 (Well Head)	28-May-19	26 Briggs St	1	0.85	0	0	0
No.	221	P190528096	SE1 (Well Head)	28-May-19	152 South Dr	2	0.68	0	0	0
No.	222	P190528097	St Eleanor's Well Field (Well #1)	28-May-19	80 Bayview Dr	2	0.74	1	0	0
No.	223	P190528098	St Eleanor's Well Field (Well #2)	28-May-19	80 Bayview Dr	2	0.94	0	0	0
No.	224	P190528099	St Eleanor's Well Field (Well #3)	28-May-19	80 Bayview Dr	2	0.82	0	0	0
No.	225	P190528100	Bernard's Quick Mart (Laundry Sink)	28-May-19	126 Bayview Dr	1	0.74	0	0	0
No.	226	P190528101	Summerside Wastewater Treatment Plant	28-May-19	15 Seaweed Rd	2	0.64	0	0	0
No.	227	P190528102	Fisheries and Oceans Coast Guard	28-May-19	240 Heather Moyses Dr	6	0.36	0	0	0

11-Jun-19										
		Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth
No.	228	P190611114	St. Eleanor's Community Center (Kitchen Sink)	11-Jun-19	1 West Drive	1	0.71	0	0	0
No.	229	P190611115	Illsley's Feed Store (Bathroom Sink)	11-Jun-19	61 Mill Cr.	2	0.60	0	0	0
No.	230	P190611116	Summerset Manor (Meter Room Sink)	11-Jun-19	15 Frank Mellish St	3	0.71	0	0	0
No.	231	P190611117	Lions Club Senior Housing (Common Room Sink)	11-Jun-19	326 Brophy St	4	0.65	0	0	0
No.	232	P190611118	Summerside Firehall (Station #1)	11-Jun-19	251 Foundry Street	6	0.80	0	0	0
No.	233	P190611119	ADL Plant (Maintenance Room Sink)	11-Jun-19	79 Water street	7	0.67	0	0	0

No.	234	P19061120	Bens Bakery Outlet Store (Bathroom Sink)	11-Jun-19	686 Water Street East	7	0.61	0	0	0
No.	235	P19061121	Tim Hortons Esso (Bakery Sink)	11-Jun-19	820 Water Street East	8	0.58	0	0	0
No.	236	P19061122	S7 Well (Well Head)	11-Jun-19	123 Walker Ave	3	0.72	0	0	0
No.	237	P19061123	S1 Well (Well Head)	11-Jun-19	411 Northmarket St	6	0.88	0	0	1
No.	238	P19061124	Wilmot Well Field (Well # 3 @ Pipe Gallery)	11-Jun-19	855 Read Drive	8	0.87	0	0	0
No.	239	P19061125	S10 Well (Well Head)	11-Jun-19	277 Greenwood Dr	2	0.68	0	0	0
No.	240	P19061126	SE4 (Well Head)	11-Jun-19	28 Briggs St	1	0.86	0	0	0
No.	241	P19061127	SE1 (Well Head)	11-Jun-19	152 South Dr	2	0.66	0	0	0
No.	242	P19061128	Summerset Manor	11-Jun-19	15 Frank Mellich St	3	0.74	0	0	0
No.	243	P19061129	St Eleanor's Well Field (Well #1)	11-Jun-19	80 Bayview Dr	2	0.66	3	0	0
No.	244	P19061130	St Eleanor's Well Field (Well #2)	11-Jun-19	80 Bayview Dr	2	0.85	0	0	0
No.	245	P19061131	St Eleanor's Well Field (Well #3)	11-Jun-19	126 Bayview Dr	1	0.71	0	0	0
No.	246	P19061132	Bernard's Quick Mart (Laundry Sink)	11-Jun-19	126 Bayview Dr	1	0.71	79	0	0
No.	247	P19061133	Summerside Wastewater Treatment Plant	11-Jun-19	15 Seaweed Rd	2	0.78	0	0	0

13-Jun-19										
Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth		
No. 248	P190322010	St Eleanor's Well Field (Well #1) (Resample)	13-Jun-19	80 Bayview Dr	2	0.77	0	0	0	0
No. 249	P190322011	St Eleanor's Well Field (Well #3) (Resample)	13-Jun-19	80 Bayview Dr	2	0.56	0	0	0	0
No. 250	P190611122	S7 Well (Well Head) (Resample)	13-Jun-19	123 Walker Ave	3	1.06	0	0	0	0

26-Jun-19										
Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth		
No. 251	P190626113	Hilsley's Feed Store (Bathroom Sink)	26-Jun-19	61 Mill Cr	2	0.72	0	0	0	0
No. 252	P190626114	Summerset Manor (Meter Room Sink)	26-Jun-19	15 Frank Mellich St	3	0.72	0	0	0	0
No. 253	P190626115	Lions Club Senior Housing (Common Room Sink)	26-Jun-19	326 Brophy St	4	0.61	0	0	0	0
No. 254	P190626116	Summerside Firehall (Station #1)	26-Jun-19	251 Foundry Street	6	0.61	0	0	0	0
No. 255	P190626117	ADL Plant (Maintenance Room Sink)	26-Jun-19	79 Water street	7	0.44	0	0	0	0
No. 256	P190626118	Bens Bakery Outlet Store (Bathroom Sink)	26-Jun-19	686 Water Street East	7	0.46	0	0	0	0
No. 257	P190626119	Tim Hortons Esso (Bakery Sink)	26-Jun-19	820 Water Street East	8	0.46	0	0	0	0
No. 258	P190626120	S7 Well (Well Head)	26-Jun-19	123 Walker Ave	3	0.63	0	0	0	0
No. 259	P190626121	S1 Well (Well Head)	26-Jun-19	411 Northmarket St	6	0.78	0	0	0	0
No. 260	P190626122	Wilmot Well Field (Well # 3 @ Pipe Gallery)	26-Jun-19	855 Read Drive	8	0.59	0	0	0	0
No. 261	P190626123	S10 Well (Well Head)	26-Jun-19	277 Greenwood Dr	2	0.77	0	0	0	0
No. 262	P190626124	SE1 (Well Head)	26-Jun-19	152 South Dr	2	0.74	0	0	0	0
No. 263	P190626125	St Eleanor's Well Field (Well #2)	26-Jun-19	80 Bayview Dr	2	0.71	0	0	0	0
No. 264	P190626126	St Eleanor's Well Field (Well #3)	26-Jun-19	80 Bayview Dr	2	0.76	0	0	0	0
No. 265	P190626127	Bernard's Quick Mart (Laundry Sink)	26-Jun-19	126 Bayview Dr	1	0.67	0	0	0	0
No. 266	P190626128	Summerside Wastewater Treatment Plant	26-Jun-19	15 Seaweed Rd	2	0.69	0	0	0	0

10-Jul-19										
Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth		
No. 267	P190710127	St Eleanor's Community Center (Kitchen Sink)	10-Jul-19	1 West Dr	1	0.67	0	0	0	0
No. 268	P190710126	Hilsley's Feed Store (Bathroom Sink)	10-Jul-19	61 Mill Cr	2	0.71	0	0	0	0
No. 269	P190710125	Summerset Manor (Meter Room Sink)	10-Jul-19	15 Frank Mellich St	3	0.69	0	0	0	0
No. 270	P190710124	Lions Club Senior Housing (Common Room Sink)	10-Jul-19	326 Brophy St	4	0.73	0	0	0	0
No. 271	P190710123	Summerside Firehall (Station #1)	10-Jul-19	251 Foundry St	6	0.26	0	0	0	0
No. 272	P190710122	ADL Plant (Maintenance Room Sink)	10-Jul-19	79 Water St	7	0.37	0	0	0	0
No. 273	P190710121	Bens Bakery Outlet Store (Bathroom Sink)	10-Jul-19	686 Water Street East	7	0.56	0	0	0	0
No. 274	P190710120	Tim Hortons Esso (Bakery Sink)	10-Jul-19	820 Water Street East	8	0.76	0	0	0	0
No. 275	P190710119	S7 Well (Well Head)	10-Jul-19	123 Walker Ave	3	0.66	0	0	0	0
No. 276	P190710118	S1 Well (Well Head)	10-Jul-19	411 Northmarket St	6	0.93	0	0	0	0
No. 277	P190710117	Wilmot Well Field (Well #2 @ Pipe Gallery)	10-Jul-19	855 Read Drive	8	0.78	0	0	0	0
No. 278	P190710116	S10 Well (Well Head)	10-Jul-19	277 Greenwood Dr	2	0.87	0	0	0	0
No. 279	P190710115	SE1 (Well Head)	10-Jul-19	152 South Dr	2	0.71	0	0	0	0
No. 280	P190710114	St Eleanor's Well Field (Well #2)	10-Jul-19	80 Bayview Dr	2	0.90	0	0	0	0
No. 281	P190710113	St Eleanor's Well Field (Well #3)	10-Jul-19	80 Bayview Dr	2	0.76	0	0	0	0
No. 282	P190710112	Bernard's Quick Mart (Laundry Sink)	10-Jul-19	126 Bayview Dr	1	0.72	0	0	0	0
No. 283	P190710111	Summerside Wastewater Treatment Plant	10-Jul-19	15 Seaweed Rd	2	0.63	0	0	0	0

23-Jul-19										
Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth		
No. 284	P190723080	St Eleanor's Community Center (Kitchen Sink)	23-Jul-19	1 West Dr	1	0.82	0	0	0	0
No. 285	P190723081	Hilsley's Feed Store (Bathroom Sink)	23-Jul-19	61 Mill Cr	2	0.70	0	0	0	0
No. 286	P190723082	Summerset Manor (Meter Room Sink)	23-Jul-19	15 Frank Mellich St	3	0.68	0	0	0	0
No. 287	P190723083	Lions Club Senior Housing (Common Room Sink)	23-Jul-19	326 Brophy St	4	0.66	0	0	0	0
No. 288	P190723084	Summerside Firehall (Station #1)	23-Jul-19	251 Foundry St	6	0.54	0	0	0	0
No. 289	P190723085	ADL Plant (Maintenance Room Sink)	23-Jul-19	79 Water St	7	0.50	0	0	0	0
No. 290	P190723086	Bens Bakery Outlet Store (Bathroom Sink)	23-Jul-19	686 Water Street East	7	0.63	0	0	0	0
No. 291	P190723087	Tim Hortons Esso (Bakery Sink)	23-Jul-19	820 Water Street East	8	0.61	0	0	0	0
No. 292	P190723088	S7 Well (Well Head)	23-Jul-19	123 Walker Ave	3	0.61	0	0	0	0
No. 293	P190723089	S1 Well (Well Head)	23-Jul-19	411 Northmarket St	6	0.71	0	0	0	0
No. 294	P190723090	Wilmot Well Field (Well #2 @ Pipe Gallery)	23-Jul-19	855 Read Drive	8	0.86	0	0	0	0
No. 295	P190723091	S10 Well (Well Head)	23-Jul-19	277 Greenwood Dr	2	0.66	0	0	0	0
No. 296	P190723092	SE1 (Well Head)	23-Jul-19	152 South Dr	2	0.70	0	0	0	0
No. 297	P190723093	St Eleanor's Well Field (Well #2)	23-Jul-19	80 Bayview Dr	2	0.93	0	0	0	0
No. 298	P190723094	St Eleanor's Well Field (Well #3)	23-Jul-19	80 Bayview Dr	2	0.93	>80	0	0	0
No. 299	P190723095	Bernard's Quick Mart (Laundry Sink)	23-Jul-19	126 Bayview Dr	1	0.54	0	0	0	0
No. 300	P190723096	Summerside Wastewater Treatment Plant	23-Jul-19	15 Seaweed Rd	2	0.60	0	0	0	0

25-Jul-19										
Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth		
No. 301	P190726019	St Eleanor's Well Field (Well #2)	25-Jul-19	80 Bayview Dr	2	0.69	0	0	0	0

6-Aug-19										
Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth		
No. 302	P190806052	St Eleanor's Community Center (Kitchen Sink)	6-Aug-19	1 West Dr	1	0.82	0	0	0	0
No. 303	P190806053	Hilsley's Feed Store (Bathroom Sink)	6-Aug-19	61 Mill Cr	2	0.70	0	0	0	0
No. 304	P190806054	Summerset Manor (Meter Room Sink)	6-Aug-19	15 Frank Mellich St	3	0.68	0	0	0	0
No. 305	P190806055	Lions Club Senior Housing (Common Room Sink)	6-Aug-19	326 Brophy St	4	0.69	0	0	0	0
No. 306	P190806056	Summerside Firehall (Station #1)	6-Aug-19	251 Foundry St	6	0.54	0	0	0	0
No. 307	P190806057	ADL Plant (Maintenance Room Sink)	6-Aug-19	79 Water St	7	0.50	0	0	0	0
No. 308	P190806058	Bens Bakery Outlet Store (Bathroom Sink)	6-Aug-19	686 Water Street East	7	0.63	0	0	0	0
No. 309	P190806059	Tim Hortons Esso (Bakery Sink)	6-Aug-19	820 Water Street East	8	0.61	0	0	0	0
No. 310	P190806060	S7 Well (Well Head)	6-Aug-19	123 Walker Ave	3	0.61	0	0	0	0
No. 311	P190806061	S1 Well (Well Head)	6-Aug-19	411 Northmarket St	6	0.71	0	0	0	0
No. 312	P190806062	Wilmot Well Field (Well #2 @ Pipe Gallery)	6-Aug-19	855 Read Drive	8	0.86	0	0	0	0
No. 313	P190806063	S10 Well (Well Head)	6-Aug-19	277 Greenwood Dr	2	0.66	0	0	0	0
No. 314	P190806064	SE1 (Well Head)	6-Aug-19	152 South Dr	2	0.70	0	0	0	0
No. 315	P190806065	St Eleanor's Well Field (Well #2)	6-Aug-19	80 Bayview Dr	2	0.93	0	0	0	0
No. 316	P190806067	St Eleanor's Well Field (Well #3)	6-Aug-19	80 Bayview Dr	2	0.93	0	0	0	0
No. 317	P190806068	Bernard's Quick Mart (Laundry Sink)	6-Aug-19	126 Bayview Dr	1	0.54	5	0	0	0
No. 318	P190806069	Summerside Wastewater Treatment Plant	6-Aug-19	15 Seaweed Rd	2	0.60	0	0	0	0

20-Aug-19									
Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth	
No. 319	P19082091	St Eleanors Community Center (Kitchen Sink)	20-Aug-19	1 West Dr	1	0.44	0	0	0
No. 320	P19082092	Ilisley's Feed Store (Bathroom Sink)	20-Aug-19	61 Mill Cr	2	0.67	0	0	0
No. 321	P19082093	Summerset Manor (Meter Room Sink)	20-Aug-19	15 Frank Mellish St	3	0.73	0	0	0
No. 322	P19082094	Lions Club Senior Housing (Common Room Sink)	20-Aug-19	326 Brophy St	4	0.73	0	0	0
No. 323	P19082095	Summerside Firehall (Station #1)	20-Aug-19	251 Foundry St	6	0.30	1	0	0
No. 324	P19082096	ADL Plant (Maintenance Room Sink)	20-Aug-19	79 Water St	7	0.62	0	0	0
No. 325	P19082097	Bens Bakery Outlet Store (Bathroom Sink)	20-Aug-19	686 Water Street East	7	0.51	0	0	0
No. 326	P19082098	Tim Hortons Esso (Bakery Sink)	20-Aug-19	820 Water Street East	8	0.76	0	0	0
No. 327	P19082099	S7 Well (Well Head)	20-Aug-19	123 Walker Ave	3	0.67	1	0	0
No. 328	P190820100	S1 Well (Well Head)	20-Aug-19	411 Northmarket St	6	0.88	0	0	0
No. 329	P190820101	Wilmot Well Field (Well #2 @ Pipe Gallery)	20-Aug-19	855 Read Drive	8	0.81	0	0	0
No. 330	P190820102	S10 Well (Well Head)	20-Aug-19	277 Greenwood Dr	2	0.77	0	0	0
No. 331	P190820103	SE1 (Well Head)	20-Aug-19	152 South Dr	2	0.71	2	0	0
No. 332	P190820104	St Eleanor's Well Field (Well #2)	20-Aug-19	80 Bayview Dr	2	0.74	24	0	0
No. 333	P190820105	St Eleanor's Well Field (Well #3)	20-Aug-19	80 Bayview Dr	2	0.73	1	0	0
No. 334	P190820106	Bernard's Quick Mart (Laundry Sink)	20-Aug-19	126 Bayview Dr	1	0.50	0	0	0
No. 335	P190820107	Summerside Wastewater Treatment Plant	20-Aug-19	15 Seaveed Rd	2	0.60	0	0	0

3-Sep-19									
Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth	
No. 336	P190903046	St Eleanors Community Center (Kitchen Sink)	3-Sep-19	1 West Dr	1	0.37	0	0	0
No. 337	P190903045	Ilisley's Feed Store (Bathroom Sink)	3-Sep-19	61 Mill Cr	2	0.60	0	0	0
No. 338	P190903044	Summerset Manor (Meter Room Sink)	3-Sep-19	15 Frank Mellish St	3	0.62	0	0	0
No. 339	P190903043	Lions Club Senior Housing (Common Room Sink)	3-Sep-19	326 Brophy St	4	0.55	0	0	0
No. 340	P190903042	Summerside Firehall (Station #1)	3-Sep-19	251 Foundry St	6	0.40	0	0	0
No. 341	P190903041	ADL Plant (Maintenance Room Sink)	3-Sep-19	79 Water St	7	0.63	0	0	0
No. 342	P190903040	Bens Bakery Outlet Store (Bathroom Sink)	3-Sep-19	688 Water Street East	7	0.51	0	0	0
No. 343	P190903039	Tim Hortons Esso (Bakery Sink)	3-Sep-19	820 Water Street East	8	0.61	0	0	0
No. 344	P190903038	S7 Well (Well Head)	3-Sep-19	123 Walker Ave	3	0.74	0	0	0
No. 345	P190903037	S1 Well (Well Head)	3-Sep-19	411 Northmarket St	6	0.79	0	0	0
No. 346	P190903036	Wilmot Well Field (Well #2 @ Pipe Gallery)	3-Sep-19	855 Read Drive	8	0.84	0	0	0
No. 347	P190903035	S10 Well (Well Head)	3-Sep-19	277 Greenwood Dr	2	0.82	0	0	0
No. 348	P190903034	SE4 Well (Well Head)	3-Sep-19	28 Briggs St	1	0.12	1	0	0
No. 349	P190903033	SE1 (Well Head)	3-Sep-19	152 South Dr	2	0.55	0	0	0
No. 350	P190903031	St Eleanor's Well Field (Well #2)	3-Sep-19	80 Bayview Dr	2	0.53	0	0	0
No. 351	P190903030	St Eleanor's Well Field (Well #3)	3-Sep-19	80 Bayview Dr	2	0.74	0	0	0
No. 352	P190903029	Bernard's Quick Mart (Laundry Sink)	3-Sep-19	126 Bayview Dr	1	0.38	0	0	0
No. 353	P190903028	Summerside Wastewater Treatment Plant	3-Sep-19	15 Seaveed Rd	2	0.70	0	0	0

19-Sep-19									
Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth	
No. 354	P190919089	St Eleanors Community Center (Kitchen Sink)	19-Sep-19	1 West Dr	1	0.27	0	0	0
No. 355	P190919090	Ilisley's Feed Store (Bathroom Sink)	19-Sep-19	61 Mill Cr	2	0.57	0	0	0
No. 356	P190919091	Summerset Manor (Meter Room Sink)	19-Sep-19	15 Frank Mellish St	3	0.41	0	0	0
No. 357	P190919092	Lions Club Senior Housing (Common Room Sink)	19-Sep-19	326 Brophy St	4	0.53	0	0	0
No. 358	P190919093	Summerside Firehall (Station #1)	19-Sep-19	251 Foundry St	6	0.56	0	0	0
No. 359	P190919094	ADL Plant (Maintenance Room Sink)	19-Sep-19	79 Water St	7	0.63	0	0	0
No. 360	P190919095	Bens Bakery Outlet Store (Bathroom Sink)	19-Sep-19	686 Water Street East	7	0.67	0	0	0
No. 361	P190919096	Tim Hortons Esso (Bakery Sink)	19-Sep-19	820 Water Street East	8	0.71	0	0	0
No. 362	P190919097	S7 Well (Well Head)	19-Sep-19	123 Walker Ave	3	0.40	0	0	0
No. 363	P190919098	S1 Well (Well Head)	19-Sep-19	411 Northmarket St	6	0.44	0	0	0
No. 364	P190919099	Wilmot Well Field (Well #2 @ Pipe Gallery)	19-Sep-19	855 Read Drive	8	0.86	0	0	0
No. 365	P190919100	S10 Well (Well Head)	19-Sep-19	277 Greenwood Dr	2	0.74	0	0	0
No. 366	P190919101	SE1 (Well Head)	19-Sep-19	152 South Dr	2	0.43	0	0	0
No. 367	P190919102	St Eleanor's Well Field (Well #2)	19-Sep-19	80 Bayview Dr	2	0.68	0	0	0
No. 368	P190919103	St Eleanor's Well Field (Well #3)	19-Sep-19	80 Bayview Dr	2	0.66	0	0	0
No. 369	P190919104	Bernard's Quick Mart (Laundry Sink)	19-Sep-19	126 Bayview Dr	1	0.61	0	0	0
No. 370	P190919105	Summerside Wastewater Treatment Plant	19-Sep-19	15 Seaveed Rd	2	0.56	0	0	0

1-Oct-19									
Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth	
No. 371	P191001088	St Eleanors Community Center (Kitchen Sink)	1-Oct-19	1 West Dr	1	0.30	0	0	0
No. 372	P191001089	Ilisley's Feed Store (Bathroom Sink)	1-Oct-19	61 Mill Cr	2	0.31	0	0	0
No. 373	P191001090	Summerset Manor (Meter Room Sink)	1-Oct-19	15 Frank Mellish St	3	0.60	0	0	0
No. 374	P191001091	Lions Club Senior Housing (Common Room Sink)	1-Oct-19	326 Brophy St	4	0.73	0	0	0
No. 375	P191001092	Summerside Firehall (Station #1)	1-Oct-19	251 Foundry St	6	0.57	0	0	0
No. 376	P191001093	ADL Plant (Maintenance Room Sink)	1-Oct-19	79 Water St	7	0.52	0	0	0
No. 377	P191001094	Bens Bakery Outlet Store (Bathroom Sink)	1-Oct-19	688 Water Street East	7	0.55	0	0	0
No. 378	P191001095	Tim Hortons Esso (Bakery Sink)	1-Oct-19	820 Water Street East	8	0.68	0	0	0
No. 379	P191001096	S7 Well (Well Head)	1-Oct-19	123 Walker Ave	3	0.77	0	0	0
No. 380	P191001097	S1 Well (Well Head)	1-Oct-19	411 Northmarket St	6	0.66	0	0	0
No. 381	P191001098	Wilmot Well Field (Well #2 @ Pipe Gallery)	1-Oct-19	855 Read Drive	8	0.83	0	0	0
No. 382	P191001099	S10 Well (Well Head)	1-Oct-19	277 Greenwood Dr	2	0.66	0	0	0
No. 383	P191001100	SE1 (Well Head)	1-Oct-19	152 South Dr	2	0.65	0	0	0
No. 384	P191001102	St Eleanor's Well Field (Well #2)	1-Oct-19	80 Bayview Dr	2	0.62	0	0	0
No. 385	P191001103	St Eleanor's Well Field (Well #3)	1-Oct-19	80 Bayview Dr	2	0.66	0	0	0
No. 386	P191001104	Bernard's Quick Mart (Laundry Sink)	1-Oct-19	126 Bayview Dr	1	0.33	0	0	0
No. 387	P191001105	Summerside Wastewater Treatment Plant	1-Oct-19	15 Seaveed Rd	2	0.56	0	0	0

15-Oct-19									
Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth	
No. 388	P191015040	St Eleanors Community Center (Kitchen Sink)	15-Oct-19	1 West Dr	1	0.37	0	0	0
No. 389	P191015041	Ilisley's Feed Store (Bathroom Sink)	15-Oct-19	61 Mill Cr	2	0.47	0	0	0
No. 390	P191015042	Summerset Manor (Meter Room Sink)	15-Oct-19	15 Frank Mellish St	3	0.48	0	0	0
No. 391	P191015043	Lions Club Senior Housing (Common Room Sink)	15-Oct-19	326 Brophy St	4	0.26	0	0	0
No. 392	P191015044	Summerside Firehall (Station #1)	15-Oct-19	251 Foundry St	6	0.33	0	0	0
No. 393	P191015045	ADL Plant (Maintenance Room Sink)	15-Oct-19	79 Water St	7	0.51	0	0	0
No. 394	P191015046	Bens Bakery Outlet Store (Bathroom Sink)	15-Oct-19	688 Water Street East	7	0.57	0	0	0
No. 395	P191015047	Tim Hortons Esso (Bakery Sink)	15-Oct-19	820 Water Street East	8	0.60	0	0	0
No. 396	P191015048	S7 Well (Well Head)	15-Oct-19	123 Walker Ave	3	0.73	0	0	0
No. 397	P191015049	S1 Well (Well Head)	15-Oct-19	411 Northmarket St	6	0.55	0	0	0
No. 398	P191015050	Wilmot Well Field (Well #2 @ Pipe Gallery)	15-Oct-19	855 Read Drive	8	0.77	0	0	0
No. 399	P191015051	S10 Well (Well Head)	15-Oct-19	277 Greenwood Dr	2	0.89	0	0	0
No. 400	P191015052	SE4 Well (Well Head)	15-Oct-19	28 Briggs St	1	0.63	0	0	0
No. 401	P191015053	SE1 (Well Head)	15-Oct-19	152 South Dr	2	0.75	0	0	0
No. 402	P191015054	St Eleanor's Well Field (Well #2)	15-Oct-19	80 Bayview Dr	2	0.89	0	0	0
No. 403	P191015055	St Eleanor's Well Field (Well #3)	15-Oct-19	80 Bayview Dr	2	0.80	0	0	0
No. 404	P191015056	Bernard's Quick Mart (Laundry Sink)	15-Oct-19	126 Bayview Dr	1	0.34	0	0	0
No. 405	P191015057	Summerside Wastewater Treatment Plant	15-Oct-19	15 Seaveed Rd	2	0.42	0	0	0
No. 406	P191015058	McIssacs Backhoeing	15-Oct-19	112 Greenwood Dr	2	0.33	0	0	0
No. 407	P191015059	Shipyard Market	15-Oct-19	370 Water St	6	0.27	0	0	0

29-Oct-19									
Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth	
No. 408	P1910129046	St Eleanors Community Center (Kitchen Sink)	29-Oct-19	1 West Dr	1	0.90	0	0	0
No. 409	P191019047	Illsley's Feed Store (Bathroom Sink)	29-Oct-19	61 Mill Cr	2	0.76	0	0	0
No. 410	P191029048	Summerset Manor (Meter Room Sink)	29-Oct-19	15 Frank Mellish St	3	0.53	0	0	0
No. 411	P191029049	Lions Club Senior Housing (Common Room Sink)	29-Oct-19	328 Brophy St	4	0.96	0	0	0
No. 412	P191029050	Summerside Firehall (Station #1)	29-Oct-19	251 Foundry St	6	0.42	0	0	0
No. 413	P191029051	ADL Plant (Maintenance Room Sink)	29-Oct-19	79 Water St	7	0.72	0	0	0
No. 414	P191029052	Bens Bakery Outlet Store (Bathroom Sink)	29-Oct-19	686 Water Street East	7	0.61	0	0	0
No. 415	P191029053	Tim Hortons Esso (Bakery Sink)	29-Oct-19	820 Water Street East	8	0.79	0	0	0
No. 416	P191029054	S7 Well (Well Head)	29-Oct-19	123 Walker Ave	3	0.84	0	0	0
No. 417	P191029055	S1 Well (Well Head)	29-Oct-19	411 Northmarket St	6	0.76	0	0	0
No. 418	P191029056	Wilmot Well Field (Well #3 @ Pipe Gallery)	29-Oct-19	855 Read Drive	8	0.80	0	0	0
No. 419	P191029057	S10 Well (Well Head)	29-Oct-19	277 Greenwood Dr	2	0.75	0	0	0
No. 420	P191029058	SE4 Well (Well Head)	29-Oct-19	26 Briggs St	1	0.88	0	0	0
No. 421	P191029059	SE1 (Well Head)	29-Oct-19	152 South Dr	2	0.68	0	0	0
No. 422	P191029060	Summerset Manor	29-Oct-19	15 Frank Mellish St	3	0.62	0	0	0
No. 423	P191029061	Bernard's Quick Mart (Laundry Sink)	29-Oct-19	126 Bayview Dr	1	0.65	0	0	0
No. 424	P191029062	Summerside Wastewater Treatment Plant	29-Oct-19	15 Seaweed Rd	2	0.69	0	0	0
No. 425	P191029063	Charly Mathews	29-Oct-19	14 MacDougall	2	0.77	0	0	0

30-Oct-19									
Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth	
No. 426	P191031015	StEleanors Wellfield Well #2	30-Oct-19	80 Bayview Dr	2	0.66	1	0	0
No. 427	P191031014	StEleanors Wellfield Well #3	30-Oct-19	80 Bayview Dr	2	0.61	0	0	0

13-Nov-19									
Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth	
No. 428	P191113104	St. Eleanor's Community Center (Kitchen Sink)	13-Nov-19	1 West Drive	1	0.99	0	0	0
No. 429	P191113103	Illsley's Feed Store (Bathroom Sink)	13-Nov-19	61 Mill Cr	2	0.58	0	0	0
No. 430	P191113102	Summerset Manor (Meter Room Sink)	13-Nov-19	15 Frank Mellish St	3	0.37	0	0	0
No. 431	P191113101	Lions Club Senior Housing (Common Room Sink)	13-Nov-19	328 Brophy St	4	0.57	0	0	0
No. 432	P191113100	Summerside Firehall (Station #1)	13-Nov-19	251 Foundry Street	6	0.45	0	0	0
No. 433	P191113099	ADL Plant (Maintenance Room Sink)	13-Nov-19	79 Water street	6	0.41	0	0	0
No. 434	P191113098	Bens Bakery Outlet Store (Bathroom Sink)	13-Nov-19	686 Water Street East	7	0.52	0	0	0
No. 435	P191113097	Tim Hortons Esso (Bakery Sink)	13-Nov-19	820 Water Street East	8	0.56	0	0	0
No. 436	P191113096	S7 Well (Well Head)	13-Nov-19	123 Walker Ave	6	0.55	0	0	0
No. 437	P191113095	S1 Well (Well Head)	13-Nov-19	411 Northmarket St	6	0.88	0	0	0
No. 438	P191113094	Wilmot Well Field (Well # 3 @ Pipe Gallery)	13-Nov-19	855 Read Drive	8	0.80	0	0	0
No. 439	P191113093	SE4 (Well Head)	13-Nov-19	26 Briggs St	1	0.97	0	0	0
No. 440	P191113092	SE1 (Well Head)	13-Nov-19	152 South Dr	2	0.59	0	0	0
No. 441	P191113091	St Eleanor's Well Field (Well #1) Raw Sample	13-Nov-19	80 Bayview Dr	2	N/A	0	0	0
No. 442	P191113090	St Eleanor's Well Field (Well #2) Raw Sample	13-Nov-19	80 Bayview Dr	2	N/A	0	0	0
No. 443	P191113089	St Eleanor's Well Field (Well #3) Raw Sample	13-Nov-19	80 Bayview Dr	2	N/A	0	0	0
No. 444	P191113088	Bernard's Quick Mart (Laundry Sink)	13-Nov-19	126 Bayview Dr	1	0.67	2	0	0
No. 445	P191113087	Summerside Wastewater Treatment Plant	13-Nov-19	15 Seaweed Rd	2	0.62	0	0	0

26-Nov-19									
Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth	
No. 446	P191126040	St. Eleanor's Community Center (Kitchen Sink)	26-Nov-19	1 West Drive	1	0.88	0	0	0
No. 447	P191126041	Illsley's Feed Store (Bathroom Sink)	26-Nov-19	61 Mill Cr	2	0.70	0	0	0
No. 448	P191126042	Summerset Manor (Meter Room Sink)	26-Nov-19	15 Frank Mellish St	3	0.61	0	0	0
No. 449	P191126043	Lions Club Senior Housing (Common Room Sink)	26-Nov-19	328 Brophy St	4	0.53	0	0	0
No. 450	P191126044	Summerside Firehall (Station #1)	26-Nov-19	251 Foundry Street	6	0.57	0	0	0
No. 451	P191126045	ADL Plant (Maintenance Room Sink)	26-Nov-19	79 Water street	6	0.63	0	0	0
No. 452	P191126046	Bens Bakery Outlet Store (Bathroom Sink)	26-Nov-19	686 Water Street East	7	0.55	0	0	0
No. 453	P191126047	Tim Hortons Esso (Bakery Sink)	26-Nov-19	820 Water Street East	8	0.59	0	0	0
No. 454	P191126048	S7 Well (Well Head)	26-Nov-19	123 Walker Ave	6	0.77	0	0	0
No. 455	P191126049	S1 Well (Well Head)	26-Nov-19	411 Northmarket St	6	0.65	0	0	0
No. 456	P191126050	Wilmot Well Field (Well # 3 @ Pipe Gallery)	26-Nov-19	855 Road Drive	8	0.81	0	0	0
No. 457	P191126051	S10 Well (Well Head)	26-Nov-19	277 Greenwood Dr	2	0.69	0	0	0
No. 458	P191126052	SE4 (Well Head)	26-Nov-19	26 Briggs St	1	0.85	0	0	0
No. 459	P191126053	SE1 (Well Head)	26-Nov-19	152 South Dr	1	0.76	0	0	0
No. 460	P191126054	Summerset Manor (Kitchen Sink)	26-Nov-19	15 Frank Mellish St	3	0.57	0	0	0
No. 461	P191126055	St Eleanor's Well Field (Well #1) Raw Sample	26-Nov-19	80 Bayview Dr	2	N/A	0	0	0
No. 462	P191126056	St Eleanor's Well Field (Well #2) Raw Sample	26-Nov-19	80 Bayview Dr	2	N/A	1	0	0
No. 463	P191126057	St Eleanor's Well Field (Well #3) Raw Sample	26-Nov-19	80 Bayview Dr	2	N/A	0	0	0
No. 464	P191126058	Bernard's Quick Mart (Laundry Sink)	26-Nov-19	126 Bayview Dr	1	0.67	0	0	0
No. 465	P191126059	Summerside Wastewater Treatment Plant	26-Nov-19	15 Seaweed Rd	2	0.40	0	0	0

10-Dec-19									
Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth	
No. 466	P191210071	St. Eleanor's Community Center (Kitchen Sink)	10-Dec-19	1 West Drive	1	0.67	0	0	0
No. 467	P191210072	Illsley's Feed Store (Bathroom Sink)	10-Dec-19	61 Mill Cr	2	0.90	0	0	0
No. 468	P191210073	Summerset Manor (Meter Room Sink)	10-Dec-19	15 Frank Mellish St	3	0.61	0	0	0
No. 469	P191210074	Lions Club Senior Housing (Common Room Sink)	10-Dec-19	328 Brophy St	4	0.61	0	0	0
No. 470	P191210075	Summerside Firehall (Station #1)	10-Dec-19	251 Foundry Street	6	0.59	0	0	0
No. 471	P191210076	ADL Plant (Maintenance Room Sink)	10-Dec-19	79 Water street	6	0.73	0	0	0
No. 472	P191210077	Bens Bakery Outlet Store (Bathroom Sink)	10-Dec-19	686 Water Street East	7	0.52	0	0	0
No. 473	P191210078	Tim Hortons Esso (Bakery Sink)	10-Dec-19	820 Water Street East	8	0.65	0	0	0
No. 474	P191210079	S7 Well (Well Head)	10-Dec-19	123 Walker Ave	6	0.65	0	0	0
No. 475	P191210080	S1 Well (Well Head)	10-Dec-19	411 Northmarket St	6	0.68	0	0	0
No. 476	P191210081	Wilmot Well Field (Well # 3 @ Pipe Gallery)	10-Dec-19	855 Read Drive	8	0.83	0	0	0
No. 477	P191210082	S10 Well (Well Head)	10-Dec-19	277 Greenwood Dr	2	0.87	0	0	0
No. 478	P191210083	SE4 (Well Head)	10-Dec-19	26 Briggs St	1	0.90	0	0	0
No. 479	P191210084	SE1 (Well Head)	10-Dec-19	152 South Dr	1	0.70	0	0	0
No. 480	P191210085	St Eleanor's Well Field (Well #1) Raw Sample	10-Dec-19	80 Bayview Dr	2	0.79	0	0	0
No. 481	P191210086	St Eleanor's Well Field (Well #2) Raw Sample	10-Dec-19	80 Bayview Dr	2	0.79	0	0	0
No. 482	P191210087	St Eleanor's Well Field (Well #3) Raw Sample	10-Dec-19	80 Bayview Dr	2	0.79	0	0	0
No. 483	P191210088	Bernard's Quick Mart (Laundry Sink)	10-Dec-19	126 Bayview Dr	1	0.46	0	0	0
No. 484	P191210089	Summerside Wastewater Treatment Plant	10-Dec-19	15 Seaweed Rd	2	0.57	0	0	0

27-Dec-19									
Sample ID	Location	Date	Address	City Sample Zone	Free Chlorine Residual	Total Coliforms	E. Coli	Background Growth	
No. 485	P191227034	St. Eleanor's Community Center (Kitchen Sink)	27-Dec-19	1 West Drive	1	0.67	0	0	0
No. 486	P191227033	Illsley's Feed Store (Bathroom Sink)	27-Dec-19	61 Mill Cr	2	0.69	0	0	0
No. 487	P191227032	Summerset Manor (Meter Room Sink)	27-Dec-19	15 Frank Mellish St	3	0.83	0	0	0
No. 488	P191227031	Lions Club Senior Housing (Common Room Sink)	27-Dec-19	328 Brophy St	4	0.45	0	0	0
No. 489	P191227030	Summerside Firehall (Station #1)	27-Dec-19	251 Foundry Street	5	0.49	0	0	0
No. 490	P191227029	ADL Plant (Maintenance Room Sink)	27-Dec-19	79 Water street	6	0.61	0	0	0
No. 491	P191227028	Bens Bakery Outlet Store (Bathroom Sink)	27-Dec-19	686 Water Street East	7	0.77	0	0	0
No. 492	P191227027	Tim Hortons Esso (Bakery Sink)	27-Dec-19	820 Water Street East	8	0.63	0	0	0
No. 493	P191227026	S7 Well (Well Head)	27-Dec-19	123 Walker Ave	6	0.86	0	0	0
No. 494	P191227025	S1 Well (Well Head)	27-Dec-19	411 Northmarket St	6	0.96	0	0	0

No. 495	P191227024	Wilmot Well Field (Well # 3 @ Pipe Gallery)	27-Dec-19	855 Read Drive	8	0.80	0	0	0
No. 496	P191227023	SE4 (Well Head)	27-Dec-19	26 Briggs St	1	0.80	0	0	0
No. 497	P191227022	SE1 (Well Head)	27-Dec-19	152 South Dr	1	0.84	0	0	0
No. 498	P191227021	Summerset Manor (Kitchen Sink)	27-Dec-19	15 Frank Mellish St	3	0.80	0	0	0
No. 499	P191227020	St Eleanor's Well Field (Well #1) Raw Sample	27-Dec-19	80 Bayview Dr	2	0.70	0	0	0
No. 500	P191227019	St Eleanor's Well Field (Well #2) Raw Sample	27-Dec-19	80 Bayview Dr	2	0.70	0	0	0
No. 501	P191227018	St Eleanor's Well Field (Well #3) Raw Sample	27-Dec-19	80 Bayview Dr	2	0.70	0	0	0
No. 502	P191227017	Bernard's Quick Mart (Laundry Sink)	27-Dec-19	128 Bayview Dr	1	0.73	0	0	0
No. 503	P191227016	Summerside Wastewater Treatment Plant	27-Dec-19	15 Seaweed Rd	2	0.63	0	0	0